

THE DEPARTMENT OF VETERANS AFFAIRS

Federal Supply Schedule

Authorized Federal Supply Schedule Price List

On-line access to contract ordering information, terms and conditions, up-to-date pricing, and the option to create an electronic delivery order are available through *GSA Advantage!*, a menu-driver database system. The INTERNET address for *GSA Advantage!* is: <http://www.gsaadvantage.gov>.

Medical Equipment and Supplies

FSC Group 65, Part II Section A

FSC Classes 6510, 6515, 6530 and 6532

Contract No. V797P-4211B

Contract Period: June 15, 2009 through June 14, 2019

For more information on ordering from Federal Supply Schedules click on the FSS Schedules button at <http://www.fss.gsa.gov>.



Alpin Surgical Specialties, Inc.

105 Lincoln Avenue

Butler, Pennsylvania 16001

Phone: 800-543-3168

Fax: 724-285-9147

www.alpinsurgical.com

Size of Business: Small

TIN: 25-1480732

Customer Information

1. Table of awarded special item numbers with appropriate cross-reference to page numbers.

<u>SIN</u>	<u>Page Numbers</u>
A-200	4-15

2. Maximum Order: \$500,000.00

3. Minimum Order: None

4. Geographic coverage (delivery area): 50 States, D.C. and Puerto Rico

5. Points of Production: Butler, Pennsylvania

6. Prices shown herein are net, discount deducted

7. Quantity discounts: None

8. Prompt payment terms: Net 30 days

9a. Government commercial credit cards accepted with no additional discount.

9b. Government commercial credit cards are accepted above the micro-purchase threshold.

10. Foreign items (list items by country of origin): None

11a. Time of delivery: Rigid Scopes – Standard repair (2 business days), Total rebuild [shaft & fibers] (7 business days); Flexible Scopes – Standard repair (2 business days), Major Repairs (5 business days), Standard Overhaul (10 business days), Small Diameter Overhaul (15 business days); Pneumatic Power Equipment and Phaco Handpieces (3 business days); Video Cameras and Battery Power Equipment (7 business days); Harmonic Scalpels (5 business days); Fiberoptic Cable Repair (10 business days) after customer approval for repair

11b. Expedited delivery: None

12. F.O.B. point: Destination to 48 contiguous states, F.O.B. point of exportation for Alaska, Hawaii and Puerto Rico.

13a. Ordering Address: 105 Lincoln Avenue, Butler Pennsylvania 16001

13b. Ordering procedures: For supplies and services, the ordering procedures, information on Blanket Purchase Agreements (BPA's), and a sample BPA can be found at the GSA/FSS Schedule homepage (fss.gsa.gov/schedules).

14. Payment address: 105 Lincoln Avenue, Butler Pennsylvania 16001

15a. Warranty Provision: The Contractor guarantees the product furnished will be free from defects in material and workmanship for a period of 90 days from date of delivery. The Contractor will replace, replaceable parts found defective for a period of 90 days with cost of replacement, including shipping charge, to be borne by the Contractor. Under no circumstances will any

equipment covered by this guarantee be returned without (a) advance notice to the Contractor, or (b) obtaining shipping instructions from the Contractor.

15b. Return Good Policy: All items must be returned in their original package within 90 days from date of delivery. In the event that a shipping error occurs due to contractor's error, contractor will pay freight both ways for return/exchange of products. If an ordering facility error occurs, the ordering facility will pay return freight. No restocking fee will apply either way. Please call 724/285-6324 for a Return Authorization Number (RA#).

16. Export packing charges, if applicable.

17. Government commercial credit card accepted above the threshold of the micro-purchase level with no additional discounts.

18. Terms and conditions of rental, maintenance and repair: See #15a.

19. Terms and conditions of installation: Not included

20a. Terms and conditions of repair parts indicating date of parts price lists and any discounts from list prices: Not applicable

20b. Terms and conditions for any other services: Not applicable

21. List of service and distribution points: Not applicable

22. List of participating dealers: Not applicable

23. Preventative maintenance: Not applicable

24a. Special attributes such as environmental attributes (e.g., recycled content, energy efficiency, and/or reduced pollutants): Not applicable

24b. If applicable, indicate that Section 508 compliance information is available on Electronic and Information Technology (EIT) supplies and services and show where full details can be found (e.g. contractor's website or other location). The EIT standards can be found at: www.Section508.gov/. Not applicable

25. Data Universal Number System (DUNS) number: 13-119-9135

26. Notification regarding registration in Central Contractor Registration (CCR) database: Currently registered; CAGE/NCAGE 55NF2.

Alpin Surgical Specialties, Inc.
Contract Number V797P-4211B

SIN #	Item #	Description	Unit of Measure	FSS Net Price
		SURGICAL INSTRUMENT REPAIR		
		SCISSORS		
A-200	R01	Standard and Tungsten Carbide	EA	3.37
A-200	R02	Delicate	EA	3.76
		RING HANDLE FORCEPS		
A-200	R03	Standard	EA	3.81
A-200	R04	Cardiovascular/Intestinal	EA	11.40
		RETRACTORS		
A-200	R05	Hand-held/Self-retaining, Blades only	EA	3.85
A-200	R06	Self-retaining	EA	4.46
		DRESSING / TISSUE FORCEPS		
A-200	R07	Standard, Vascular, and Tungsten Carbide Without Insert Replacement	EA	4.37
		BONE INSTRUMENTS		
A-200	R08	Single Action	EA	16.70
A-200	R09	Double Action	EA	16.70
A-200	R10	Kerrison, Type	EA	15.35
A-200	R11	Chisels, Osteotomes, Elevators, Curettes & Gouges	EA	3.75
		NEEDLE HOLDERS		
A-200	R12	Standard or Tungsten Carbide without Insert Replacement	EA	4.21
A-200	R13	Tungsten Carbide Replacement	EA	17.25
		MICRO INSTRUMENTATION		
A-200	R14	Scissors	EA	6.60
A-200	R15	Tying, 1x2, Bayonet, etc.	EA	7.50
A-200	R16	Alligator/Grasping	EA	19.38
A-200	R17	Needle Holders	EA	7.90

Alpin Surgical Specialties, Inc.
Contract Number V797P-4211B

SIN #	Item #	Description	Unit of Measure	FSS Net Price
		FLEXIBLE ENDOSCOPE REPAIR		
		Air / Water Repairs		
A-200	R101-AW1	Unblock A/W Channel	EA	64.65
A-200	R101-AW2	Replace A/W Nozzle	EA	89.55
A-200	R101-AW3	Replace A/W Channel	EA	398.00
		Bending Section Repairs		
A-200	R101-BS1	Replace Bending Rubber	EA	148.25
		Angulation Repairs		
A-200	R101-AR1	Minor Angulation Adjustment	EA	124.37
A-200	R101-AR2	Full Angulation Adjustment	EA	223.85
A-200	R101-AR3	Angulation Wire Replacement	EA	846.00
A-200	R101-AR4	Wire Replacement (bronchoscope)	EA	1,716.35
		Biopsy Channel Repairs		
A-200	R101-BC1	Replace Upper & Lower Biopsy Channel	EA	1,269.00
A-200	R101-BC2	Replace Bronchoscope Biopsy Channel	EA	1,766.10
A-200	R101-BC3	Unclog Biopsy Channel	EA	124.37
		Eye Piece Repairs		
A-200	R101-EP1	Rebuild Eyepiece (fluid invasion, dust, etc.)	EA	223.85
		Control Body Repairs		
A-200	R101-CB1	Repair Damaged Control Body and Reseal	EA	149.25
A-200	R101-CB2	Repair Leaking Aux. Water Connector	EA	89.55
A-200	R101-CB3	Reseal S-Cover	EA	149.25
		Light Guide Tube / Connector Repairs		
A-200	R101-LG1	Tighten Light Guide Connector	EA	14.92
A-200	R101-LG2	Reseal Light Guide Connector	EA	64.60
A-200	R101-LG3	Replace Light Guide	EA	1,741.25
		Insertion Tube Repairs		
A-200	R101-IT1	Repair "Bite" or Dent	EA	124.37
A-200	R101-IT2	Repair Buckle at Control Body Boot (install boot extender)	EA	298.00
A-200	R101-IT3	Replace Insertion Tube (includes new angulation cables, biopsy channel, angulation & BSR)	EA	2,980.00
		Fluid Invasion Repairs		
A-200	R101-FL1	Minor Fluid Invasion	EA	547.25
A-200	R101-FL2	Major Fluid Invasion (<i>Vacuum Oven</i>)	EA	845.75
		Suction Channel Repairs		
A-200	R101-SC1	Replace Suction Channel (in large tube)	EA	422.80
A-200	R101-SC2	Unblock Suction Channel	EA	149.25

**Alpin Surgical Specialties, Inc.
Contract Number V797P-4211B**

SIN #	Item #	Description	Unit of Measure	FSS Net Price
		RIGID ENDOSCOPE REPAIR		
		<u>LEVEL ONE:</u>		
		A. Completely disassemble and clean entire optical system		
		B. Functional testing of all mechanical parts		
		C. Laser adjustment of optical system and ocular lens		
		D. Fiberoptic light connection rebonding and polishing		
		E. Hermetical sealing of scope		
		F. Repair optical system (includes level one plus any damaged rod lens or objective lens)		
		G. Recalibrate optical lens spacers		
		H. Capped price with no additional parts charge		
A-200	R102-1A	Repair made within our facility	EA	492.55
A-200	R102-1B	Repair made outside our facility	EA	562.55
		<u>LEVEL TWO:</u>		
		A. Complete rebuilding of scope (includes above plus shaft/fibers)		
		B. Replacement of inner and outer tubing		
		C. Replacement of fiberoptic light bundle		
		D. Capped price with no additional parts charge		
		* Scopes with an image bundle, off-set operative scopes, scopes 2.7 mm and smaller in diameter, scopes with more than 6 rod lenses, and scopes deemed non-repairable by manufacturer are not included.		
A-200	R102-2A	Repair made within our facility	EA	771.15
A-200	R102-2B	Repair made outside our facility	EA	841.15

Alpin Surgical Specialties, Inc.
Contract Number V797P-4211B

SIN #	Item #	Description	Unit of Measure	FSS Net Price
		PNEUMATIC-POWERED EQUIPMENT REPAIR		
		<u>Level I</u>		
		This level of repair includes:		
		• Disassemble		
		• Clean Motor		
		• Re-lube		
		• Assemble		
		• Seal		
		• Clean		
		• Test		
A-200	R105-1A	Repair made within our facility	EA	174.15
A-200	R105-1B	Repair made outside our facility	EA	209.15
		<u>Level II</u>		
		This level of repair includes:		
		• Disassemble		
		• Clean Motor		
		• Replace O-rings		
		• Assemble		
		• Seal		
		• Clean		
		• Test		
A-200	R105-2A	Repair made within our facility	EA	273.65
A-200	R105-2B	Repair made outside our facility	EA	308.65
		<u>Level III</u>		
		This level of repair includes:		
		• Disassemble		
		• Clean Motor		
		• Replace O-rings		
		• Bearings		
		• Swivel Repair		
		• Lever Mount Repair		
		• Poppet Spring		
		• Coupling		
		• Assemble		
		• Seal		
		• Clean		
		• Test		
A-200	R105-3A	Repair made within our facility	EA	422.87
A-200	R105-3B	Repair made outside our facility	EA	457.87

**Alpin Surgical Specialties, Inc.
Contract Number V797P-4211B**

SIN #	Item #	Description	Unit of Measure	FSS Net Price
		<u>Level IV</u>		
		This level of repair includes:		
		• Disassemble		
		• Clean Motor		
		• Replace O-rings		
		• Bearings		
		• Swivel Repair		
		• Lever Mount Repair		
		• Poppet Spring		
		• Coupling		
		• Rebuild Motor		
		• Output Assembly		
		• Gear Mesh		
		• Gear Box		
		• Valve		
		• Assemble		
		• Seal		
		• Clean		
		• Test		
A-200	R105-4A	Repair made within our facility	EA	472.65
A-200	R105-4B	Repair made outside our facility	EA	507.65
** The above does not apply to pneumatic hand pieces that are discontinued models, have custom machined parts, have housing or air-port inlet damage or includes replacement of couplers. These repairs would be individually quoted. **				
A-200	R105-AIR	<u>Air Hoses</u>	EA	129.35
		This repair includes:		
		• Replace Inner & Outer Sheath		
		• Rebuild Check-Valve Assemble		
		• Realign Coupler		
** The above does not include special length hose (greater than 10 foot). These repairs would be individually quoted. **				

**Alpin Surgical Specialties, Inc.
Contract Number V797P-4211B**

SIN #	Item #	Description	Unit of Measure	FSS Net Price
		VIDEO CAMERA REPAIR		
		STRYKER 888/988/1088 NON-AUTOCLAVABLE CAMERAS		
		Level 1 Repairs:		
		• Head cable replacement		
		• Camera head seal replacement		
		• Pin connector replacement		
		• Re-bond optics		
		• Clean and/or repair CCD		
		• Center prism		
		• Burn in		
		• Calibrate		
A-200	R108-STK1-A	Repair made within our facility	EA	1,189.00
A-200	R108-STK1-B	Repair made outside our facility	EA	1,259.00
		Level 2 Repairs:		
		• All repair functions of level 1		
		• Replacement of Bad Prism		
A-200	R108-STK2-A	Repair made within our facility	EA	1,915.40
A-200	R108-STK2-B	Repair made outside our facility	EA	1,985.40
		ALL THREE CHIP CAMERAS:		
		Any camera requiring repairs due to misuse and/or abuse will be charged at the appropriate level above, as well as any additional costs of materials and labor. As well as any cameras that have been inappropriately repaired in the past will be on a quote only basis.		
		NOTE:		
		<i>All Stryker 3-chip camera heads with the Molex damaged will have all essential parts replaced and will not be hard wired to the prism. Alpin Surgical Specialties molds strain relief to cable for additional support and durability.</i>		

**Alpin Surgical Specialties, Inc.
Contract Number V797P-4211B**

SIN #	Item #	Description	Unit of Measure	FSS Net Price
		DYONICS ED3 CAMERAS		
		Level 1 Repairs		
		• Head cable replacement		
		• Camera head seal replacement		
		• Pin connector replacement		
		• Re-bond optics		
		• Clean and/or repair CCD		
		• Center prism		
		• Burn in		
		• Calibrate		
A-200	R108-DY-1	Repair made outside our facility	EA	1,060.00
		Level 2 Repairs		
		• All repair functions of Level 1		
		• Replacement of bad prism		
A-200	R108-DY-2	Repair made outside our facility	EA	1,985.40
		Any camera requiring additional parts (i.e. body replacement) will be quoted. Alpin Surgical Specialties molds strain relief to cable for additional support and durability.		
		LINVATEC IM 3320 AUTOCLAVABLE CAMERAS		
		Level 1 Repairs		
		• Head cable replacement		
		• Camera head seal replacement		
		• Pin connector replacement		
		• Re-bond optics		
		• Clean and/or repair CCD		
		• Center prism		
		• Burn in		
		• Calibrate		
A-200	R108-LIN-1	Repair made outside our facility	EA	1,985.40
		Level 2 Repairs		
		• All repair functions of Level 1		
		• Replacement of bad prism		
A-200	R108-LIN-2	Repair made outside our facility	EA	2,353.55

**Alpin Surgical Specialties, Inc.
Contract Number V797P-4211B**

SIN #	Item #	Description	Unit of Measure	FSS Net Price
		STORZ IMAGE I CAMERAS		
		Level 1 Repairs		
A-200	R108-STZ-1A	Standard Repair made within our facility	EA	1,288.55
A-200	R108-STZ-1B	Standard Repair made outside our facility	EA	1,358.55
A-200	R108-STZAC-1A	Autoclavable Repair made within our facility	EA	2,283.55
A-200	R108-STZAC-1B	Autoclavable Repair made outside our facility	EA	2,353.55
		• Head cable replacement		
		• Camera head seal replacement		
		• Pin connector replacement		
		• Re-bond optics		
		• Clean and/or repair CCD		
		• Center prism		
		• Burn in		
		• Calibrate		
		Level 2 Repairs		
		• All repair functions of Level 1		
		• Replacement of bad prism		
A-200	R108-STZ-2B	Repair made outside our facility	EA	3,647.00
		OLYMPUS OTVS7 SINGLE CHIP CAMERAS		
		Level 1 Repairs		
A-200	R108-OLY-STD	Standard Repair made outside our facility	EA	1,159.55
A-200	R108-OLY-AC	Autoclavable Repair made outside our facility	EA	2,055.00
		• Head cable replacement		
		• Camera head seal replacement		
		• Pin connector replacement		
		• Re-bond optics		
		• Clean and/or repair CCD		
		• Center prism		
		• Burn in		
		• Calibrate		

Alpin Surgical Specialties, Inc.
Contract Number V797P-4211B

SIN #	Item #	Description	Unit of Measure	FSS Net Price
		COUPLERS/BEAMSPLITTERS		
		• Most model couplers except below		
A-200	R108-CPL-A	Repair made within our facility	EA	293.55
A-200	R108-CPL-B	Repair made outside our facility	EA	363.55
		• Couplers with focus and zoom ring		
A-200	R108-CPLF-A	Repair made within our facility	EA	447.75
A-200	R108-CPLF-B	Repair made outside our facility	EA	517.75
		• Precision Optics		
A-200	R108-CPLP-A	Repair made within our facility	EA	592.00
A-200	R108-CPLP-B	Repair made outside our facility	EA	662.00
		• Autoclavable couplers		
A-200	R108-CPLAC-A	Repair made within our facility	EA	592.00
A-200	R108-CPLAC-B	Repair made outside our facility	EA	662.00
		• Stryker autoclavable couplers		
A-200	R108-CPLSK-A	Repair made within our facility	EA	726.35
A-200	R108-CPLSK-B	Repair made outside our facility	EA	796.35
		• Most minor mechanical repairs		
A-200	R108-CPLM-A	Repair made within our facility	EA	174.15
A-200	R108-CPLM-B	Repair made outside our facility	EA	244.15
		• Beamsplitters		
A-200	R108-CPLBM-A	Repair made within our facility	EA	592.00
A-200	R108-CPLBM-B	Repair made outside our facility	EA	662.00
		Couplers quoted separately.		
		Any camera/coupler requiring additional parts (i.e. body replacement) will be quoted.		

**Alpin Surgical Specialties, Inc.
Contract Number V797P-4211B**

SIN #	Item #	Description	Unit of Measure	FSS Net Price
		POWERED INSTRUMENTS - ELECTRIC / BATTERY		
		Battery Rebuild (including, but not limited to):		
		• Hall Versipower		
		• Stryker Orthopower 90, System 2000 and System 4000		
		• 3M		
		• Dyonics		
A-200	R106-BR-A	Repair made within our facility	EA	263.70
A-200	R106-BR-B	Repair made outside our facility	EA	298.70
		Preventative Maintenance:		
		• Replace all worn o-rings and seals		
		• Clean and lubricate all internal parts		
A-200	R106-PREV-A	Repair made within our facility	EA	437.80
A-200	R106-PREV-B	Repair made outside our facility	EA	472.80
		Partial Rebuild:		
		• Refurbish or replace motor components		
		• Refurbish cable connectors		
		• Replace up to 2 bearings, as well as all worn o-rings and seals		
		• Clean and lubricate all internal parts		
A-200	R106-PART-A	Repair made within our facility	EA	636.80
A-200	R106-PART-B	Repair made outside our facility	EA	671.80
		Complete Rebuild:		
		• Motor rebuild or rewind:		
		• Replace all worn bearings, small gears, o-rings, and seals		
		• Clean and lubricate all internal parts		
A-200	R106-COMP-A	Repair made within our facility	EA	1,089.55
A-200	R106-COMP-B	Repair made outside our facility	EA	1,124.55
		Cable Replacement:		
		• For Dyonics, Linvatec, and Stryker		
A-200	R106-CABLE-A	Repair made within our facility	EA	497.50
A-200	R106-CABLE-B	Repair made outside our facility	EA	532.50
		Electric repairs require a minimum of 48-hour turn around.		
		We do provide quotes on request, although to quote an electrical repair entails a process of elimination. Due to this, you will receive a high or low quote. Motor and cable replacement will be a minimum of 5-7 working days.		

Alpin Surgical Specialties, Inc.
Contract Number V797P-4211B

SIN #	Item #	Description	Unit of Measure	FSS Net Price
		PHACO HANDPIECE		
		Minor Repairs:		
		• Tip removal from horn		
		• Reform case around horn		
		• Clear blockage		
A-200	R103-MIN	Repair made outside our facility	EA	258.90
		Other Repairs:		
		• Replace connector		
A-200	R103-RC	Repair made outside our facility	EA	607.15
		• Replace connector and cable		
A-200	R103-RCC	Repair made outside our facility	EA	880.75
		• Reseal o-rings		
A-200	R103-RO	Repair made outside our facility	EA	756.40
		Total Refurbishment: (Includes)		
		• Recondition or replace piezo crystals, electrodes and o-rings		
		• Replace cable and connector		
		• Reseal and encapsulate electrical analysis and diagnostics		
A-200	R103-TOTAL	Repair made outside our facility	EA	1,323.55
		Total Refurbishment: Exceptions from Standard models at this time.		
		• Alcon Neosonix		
A-200	R103-ALCON	Repair made outside our facility	EA	2,617.00
		• Infinity Neosonix		
A-200	R103-NEOSONIX	Repair made outside our facility	EA	2,617.00
		• Infinity Ozil		
A-200	R103-OZIL	Repair made outside our facility	EA	1,821.00
		Standard Turnaround Time: 72 hours (based on approval of repair)		
		Expedited Repairs Available: 48 hours \$300.00		
		24 hours \$425.00		
		Standard Warranty: 6 months		
		Extended Warranty Available: 9 months \$300.00		
		1 year \$575.00		

Alpin Surgical Specialties, Inc.
Contract Number V797P-4211B

SIN #	Item #	Description	Unit of Measure	FSS Net Price
		HARMONIC SCALPEL		
A-200	R117	Refurbish: • Generation 1, 2 and 3		
		Repair made outside our facility	EA	795.00
		The handpiece is then disassembled and receives a detailed and comprehensive repair, including the replacement of: piezo electric crystals; nose cone, resonator and threads; seals and o-rings; cable and connector; moulded strain relief.		
		FIBEROPTIC CABLE REPAIR		
		Fiberoptic Cables (up to 8-foot lengths) • up to 5.5 mm bundle		
A-200	R107-5.5	Repair made outside our facility	EA	156.30
		• up to 6.5 mm bundle		
A-200	R107-6.5	Repair made outside our facility	EA	161.25
		• bifurcated bundles		
A-200	R107-BIF	Repair made outside our facility	EA	235.90
		• liquid light bundle conversion		
A-200	R107-LIQ	Repair made outside our facility	EA	176.20
		Additional Charges		
A-200	R107-HW	• Rework or replace hardware	EA	61.75
A-200	R107-SIL	• Replace silicone sheath	EA	No Charge
A-200	R107-SHE	• Replace special sheath	EA	41.85
		Repairs made outside our facility		