



**GENERAL SERVICES ADMINISTRATION
FEDERAL SUPPLY SERVICE
AUTHORIZED FEDERAL SUPPLY SCHEDULE PRICE LIST**

**MULTIPLE AWARD SCHEDULE (MAS)
CATEGORY: INFORMATION TECHNOLOGY**

Note: Contractor has been awarded under the Cooperative Purchasing & Disaster Recovery programs.

Trinity Dynamics, Inc.

11003 Bluegrass Parkway, Suite 600

Louisville, KY 40299-2395

Phone: (502) 240-6100

Fax: (502) 240-6140

<https://www.trinitydynamics.net/>

CONTRACT NUMBER: GS-35F-0070R

PERIOD COVERED BY CONTRACT:

October 28, 2004 through October 27, 2024

BUSINESS SIZE:

Small Business

Pricelist current through modification PA-0041
Effective date June 24, 2020

On line access to contract ordering information, terms and conditions, up to date pricing, and the option to create an electronic delivery order are available through GSA Advantage!®, a menu driven database system. The INTERNET address GSA Advantage!® is: GSAAAdvantage.gov. For more information on ordering from Federal Supply Schedules go to the GSA Schedules page at GSA.gov.

CUSTOMER INFORMATION

1a. AUTHORIZED SPECIAL ITEM NUMBERS (SINs):

<u>SIN</u>	<u>DESCRIPTION</u>
33411	Purchasing of new electronic equipment
811212	Maintenance of Equipment, Repair Services and/or Repair/Spare Parts
OLM	Order-Level Materials (OLM)

1b. Lowest Priced Model Number and Price for each SIN: See Price List

1c. SERVICES OFFERED: See Price List

2. MAXIMUM ORDER PER SIN:

<u>SIN</u>	<u>MAXIMUM ORDER</u>
33411	\$500,000 per SIN/Order
811212	\$500,000 per SIN/Order
OLM	\$250,000 per SIN/Order

3. MINIMUM ORDER LIMITATION: \$100

4. GEOGRAPHIC COVERAGE (DELIVERY AREA): The geographic scope of this contract is the 48 contiguous states, Alaska, Hawaii, Puerto Rico, Washington, DC, and U.S. Territories

5. POINT OF PRODUCTION: United States

6. BASIC DISCOUNT: Prices listed are net, discounts have been deducted and the industrial funding fee has been added

7. QUANTITY DISCOUNT: None

8. PROMPT PAYMENT TERMS: 1% - 15 Days; NET 30. Information for Ordering Offices: Prompt payment terms cannot be negotiated out of the contractual agreement in exchange for other concessions.

9a. GOVERNMENT PURCHASE CARDS ARE ACCEPTED UP TO THE MICRO-PURCHASE THRESHOLD.

9b. GOVERNMENT PURCHASE CARDS ARE ACCEPTED ABOVE THE MICRO-PURCHASE THRESHOLD.

10. **FOREIGN ITEMS:** None
- 11a. **TIME OF DELIVERY:** 30 Days ARO
- 11b. **EXPEDITED DELIVERY:** Contact Contractor
- 11c. **OVERNIGHT AND 2-DAY DELIVERY:** Contact Contractor
- 11d. **URGENT REQUIREMENTS:** Contact Contractor
12. **F.O.B. POINT:** Destination
- 13a. **ORDERING ADDRESS:** Trinity Dynamics, Inc.
11003 Bluegrass Parkway, Suite 600
Louisville, KY 40299-2395
- 13b. **ORDERING PROCEDURES:** For supplies and services, the ordering procedures, information on Blanket Purchase Agreements (BPA's) are found in Federal Acquisition Regulation (FAR) 8.405-3.
14. **PAYMENT ADDRESS:** Same as Ordering Address
15. **WARRANTY PROVISION:** Standard Commercial Warranty
16. **EXPORT PACKING CHARGES:** Not Applicable
17. **TERMS AND CONDITIONS OF GOVERNMENT PURCHASE CARD ACCEPTANCE:**
Will be accepted above the micro-purchase threshold
18. **TERMS AND CONDITIONS OF RENTAL:** Not Applicable
19. **TERMS AND CONDITIONS OF INSTALLATION:** Not Applicable
20. **TERMS AND CONDITIONS OF REPAIR PARTS:** Not Applicable
- 20a. **TERMS AND CONDITIONS FOR ANY OTHER SERVICES:** Not Applicable

21. **LIST OF SERVICE AND DISTRIBUTION POINTS:** Not Applicable

22. **LIST OF PARTICIPATING DEALERS:**

VHSS – Veterans Healthcare Supply Solutions

13949 Alvarez Road, Suite 300

Jacksonville, FL 32218

Phone: 904-638-5519

Fax: 904-638-5522

Email: gskura@vhss1.com

POC: Gary Skura, President

23. **PREVENTIVE MAINTENANCE:** Not Applicable

24a. **SPECIAL ATTRIBUTES:** Not Applicable

24b. **SECTION 508 COMPLIANCE INFORMATION:**

<https://www.trinitydynamics.net/government/>

25. **DATA UNIVERSAL NUMBER SYSTEM (DUNS) NUMBER:** 038211830

26. **CONTRACTOR HAS REGISTERED IN THE SYSTEM FOR AWARD MANAGEMENT (SAM) DATABASE.**

**TERMS AND CONDITIONS APPLICABLE TO PURCHASE OF
NEW ELECTRONIC EQUIPMENT (SPECIAL ITEM NUMBER 33411)**

1. MATERIAL AND WORKMANSHIP

All equipment furnished hereunder must satisfactorily perform the function for which it is intended.

2. ORDER

Written orders, EDI orders (GSA Advantage! and FACNET), credit card orders, and orders placed under blanket purchase agreements (BPA) agreements shall be the basis for purchase in accordance with the provisions of this contract. If time of delivery extends beyond the expiration date of the contract, the Contractor will be obligated to meet the delivery and installation date specified in the original order. For credit card orders and BPAs, telephone orders are permissible.

3. TRANSPORTATION OF EQUIPMENT

FOB DESTINATION. Prices cover equipment delivery to destination, for any location within the geographic scope of this contract.

4. INSTALLATION AND TECHNICAL SERVICES

a. **INSTALLATION.** When the equipment provided under this contract is not normally self-installable, the Contractor's technical personnel shall be available to the ordering activity, at the ordering activity's location, to install the equipment and to train ordering activity personnel in the use and maintenance of the equipment. The charges, if any, for such services are listed below, or in the price schedule:

b. **INSTALLATION, DEINSTALLATION, REINSTALLATION**

The Davis-Bacon Act (40 U.S.C. 276a-276a-7) provides that contracts in excess of \$2,000 to which the United States or the District of Columbia is a party for construction, alteration, or repair (including painting and decorating) of public buildings or public works with the United States, shall contain a clause that no laborer or mechanic employed directly upon the site of the work shall received less than the prevailing wage rates as determined by the Secretary of Labor. The requirements of the Davis-Bacon Act do not apply if the construction work is incidental to the furnishing of supplies, equipment, or services. For example, the requirements do not apply to simple installation or alteration of a public building or public work that is incidental to furnishing supplies or equipment under a supply contract. However, if the construction, alteration or repair is segregable and exceeds \$2,000, then the requirements of the Davis-Bacon Act applies.

The ordering activity issuing the task order against this contract will be responsible for proper administration and enforcement of the Federal labor standards covered by the Davis-Bacon Act. The proper Davis-Bacon wage determination will be issued by the ordering activity at the time a request for quotations is made for applicable construction classified installation, deinstallation, and reinstallation services under SIN 33411.

c. **OPERATING AND MAINTENANCE MANUALS.** The Contractor shall furnish the ordering activity with one (1) copy of all operating and maintenance manuals which are normally provided with the equipment being purchased.

d. **TECHNICAL SERVICES.** With a valid Maintenance Agreement, you receive 7x24 emergency tele-support, access to the Contractor's 800-Help Desk and Technical Center during normal business hours, access to the Contractor's 800-Video Testing Facilities, on-site failed parts replacement within one business week, remote diagnostics and troubleshooting, and on-site problem resolution.

Help Desk/Technical Center/Video Testing: (800) 261-9008

Remote Diagnostic and Troubleshooting: (502) 657-2028

5. INSPECTION/ACCEPTANCE

The Contractor shall only tender for acceptance those items that conform to the requirements of this contract. The ordering activity reserves the right to inspect or test any equipment that has been tendered for acceptance. The ordering activity may require repair or replacement of nonconforming equipment at no increase in contract price. The ordering activity must exercise its postacceptance rights (1) within a reasonable time after the defect was discovered or should have been discovered; and (2) before any substantial change occurs in the condition of the item, unless the change is due to the defect in the item.

6. WARRANTY

- a. Unless specified otherwise in this contract, the Contractor's standard commercial warranty as stated in the contract's commercial pricelist will apply to this contract.
- b. The Contractor warrants and implies that the items delivered hereunder are merchantable and fit for use for the particular purpose described in this contract.
- c. **Limitation of Liability.** Except as otherwise provided by an express or implied warranty, the Contractor will not be liable to the ordering activity for consequential damages resulting from any defect or deficiencies in accepted items.
- d. If inspection and repair of defective equipment under this warranty will be performed at the Contractor's plant, the address is as follows:

Trinity Dynamics, Inc.
11003 Bluegrass Parkway, Suite 600
Louisville, KY 40299-2395

7. PURCHASE PRICE FOR ORDERED EQUIPMENT

The purchase price that the ordering activity will be charged will be the ordering activity purchase price in effect at the time of order placement, or the ordering activity purchase price in effect on the installation date (or delivery date when installation is not applicable), whichever is less.

8. RESPONSIBILITIES OF THE CONTRACTOR

The Contractor shall comply with all laws, ordinances, and regulations (Federal, State, City or otherwise) covering work of this character, and shall include all costs, if any, of such compliance in the prices quoted in this offer.

9. TRADE-IN OF INFORMATION TECHNOLOGY EQUIPMENT

When an ordering activity determines that Information Technology equipment will be replaced, the ordering activity shall follow the contracting policies and procedures in the Federal Acquisition Regulation (FAR), the policies and procedures regarding disposition of information technology excess personal property in the Federal Property Management Regulations (FPMR) (41 CFR 101-43.6), and the policies and procedures on exchange/sale contained in the FPMR (41 CFR part 101-46).

**TERMS AND CONDITIONS APPLICABLE TO MAINTENANCE OF EQUIPMENT,
REPAIR SERVICES AND/OR REPAIR/SPARE PARTS (SPECIAL ITEM NUMBER
811212)**

1. SERVICE AREAS

- a. The maintenance rates listed herein are applicable to any ordering activity location within the Continental US.
- b. When repair services cannot be performed at the ordering activity installation site, the repair services will be performed at the Contractor's plant listed below:

Trinity Dynamics, Inc.
11003 Bluegrass Parkway, Suite 600
Louisville, KY 40299-2395

2. MAINTENANCE ORDER

- a. Agencies may use written orders, EDI orders, credit card orders, or BPAs, for ordering maintenance under this contract. The Contractor shall confirm orders within fifteen (15) calendar days from the date of receipt, except that confirmation of orders shall be considered automatic for renewals for maintenance (Special Item Number 811212). Automatic acceptance of order renewals for maintenance service shall apply for machines which may have been discontinued from use for temporary periods of time not longer than 120 calendar days. If the order is not confirmed by the Contractor as prescribed by this paragraph, the order shall be considered to be confirmed by the Contractor.
- b. The Contractor shall honor orders for maintenance for the duration of the contract period or a lesser period of time, for the equipment shown in the pricelist. Maintenance service shall commence on a mutually agreed upon date, which will be written into the maintenance order. Maintenance orders shall not be made effective before the expiration of any applicable maintenance and parts guarantee/warranty period associated with the purchase of equipment. Orders for maintenance service shall not extend beyond the end of the contract period.
- c. Maintenance may be discontinued by the ordering activity on thirty (30) calendar days written notice, or shorter notice when agreed to by the Contractor; such notice to become effective thirty (30) calendar days from the date on the notification. However, the ordering activity may extend the original discontinuance date upon written notice to the Contractor, provided that such notice is furnished at least ten (10) calendar days prior to the original discontinuance date.
- d. Annual Funding. When annually appropriated funds are cited on a maintenance order, the period of maintenance shall automatically expire on September 30th of the contract period, or at the end of the contract period, whichever occurs first. Renewal of a maintenance order citing the new appropriation shall be required, if maintenance is to continue during any remainder of the contract period.
- e. Cross-year Funding Within Contract Period. Where an ordering activity's specific appropriation authority provides for funds in excess of a 12 month, fiscal year period, the ordering activity may place an order under this schedule contract for a period up to the expiration of the contract period, notwithstanding the intervening fiscal years.
- f. Ordering activities should notify the Contractor in writing thirty (30) calendar days prior to the expiration of maintenance service, if maintenance is to be terminated at that time. Orders for continued maintenance will be required if maintenance is to be continued during the subsequent period.

3. REPAIR SERVICE AND REPAIR PARTS/SPARE PARTS ORDERS

- a. Agencies may use written orders, EDI orders, credit card orders, blanket purchase agreements (BPAs), or small order procedures for ordering repair service and/or repair parts/spare parts under this contract. Orders for repair service shall not extend beyond the end of the contract period.
- b. When repair service is ordered, only one chargeable repairman shall be dispatched to perform repair service, unless the ordering activity agrees, in advance, that additional repair personnel are required to effect repairs.

4. LOSS OR DAMAGE

When the Contractor removes equipment to his establishment for repairs, the Contractor shall be responsible for any damage or loss, from the time the equipment is removed from the ordering activity installation, until the equipment is returned to such installation.

5. SCOPE

- a. The Contractor shall provide maintenance for all equipment listed herein, as requested by the ordering activity during the contract term. Repair service and repair parts/spare parts shall apply exclusively to the equipment types/models within the scope of this Multiple Award Schedule.
- b. Equipment placed under maintenance service shall be in good operating condition.
 - (1) In order to determine that the equipment is in good operating condition, the equipment shall be subject to inspection by the Contractor, without charge to the ordering activity.
 - (2) Costs of any repairs performed for the purpose of placing the equipment in good operating condition shall be borne by the Contractor, if the equipment was under the Contractor's guarantee/warranty or maintenance responsibility prior to the effective date of the maintenance order.
 - (3) If the equipment was not under the Contractor's responsibility, the costs necessary to place the equipment in proper operating condition are to be borne by the ordering activity, in accordance with the provisions of Special Item Number 811212 (or outside the scope of this contract).

6. RESPONSIBILITIES OF THE ORDERING ACTIVITY

- a. Ordering activity personnel shall not perform maintenance or attempt repairs to equipment while such equipment is under the purview of a maintenance order, unless agreed to by the Contractor.
- b. Subject to security regulations, the ordering activity shall permit access to the equipment which is to be maintained or repaired.

7. RESPONSIBILITIES OF THE CONTRACTOR

For equipment not covered by a maintenance contract or warranty, the Contractor's repair service personnel shall complete repairs as soon as possible after notification by the ordering activity that service is required. Within the service areas, this repair service should normally be done within 4 hours after notification.

8. REPAIR SERVICE RATE PROVISIONS

- a. The Contractor shall bear all costs of maintenance, including labor, parts, and such other expenses as are necessary to keep the equipment in good operating condition, provided that the required repairs are not occasioned by fault or negligence of the ordering activity.
- b. ON-SITE COVERAGE. Provides on-site technical support dispatched the following business day for service calls received prior to 12 noon customer-site time, if the problem cannot be resolved remotely. Arrival on-site depends on travel requirements and could be impacted by conditions beyond the Contractor's control (ie. Travel/weather delays, etc.).

- c. **REGULAR HOURS.** The basic monthly rate for each make and model of equipment shall entitle the ordering activity to maintenance service during the Contractor's normal business hours, 8:30am to 5:00pm EST, Monday through Friday, exclusive of holidays observed at the ordering activity location.
- d. **AFTER HOURS.** Should the ordering activity require that maintenance be performed outside of Regular Hours, charges for such maintenance, if any, will be specified in the price list. Periods of less than one hour will be prorated to the nearest quarter hour.
- e. **MAINTENANCE HIGHLIGHTS.** Include 7x24 emergency tele-support, access to the Contractor's 1-800 Help Desk and Technical Center during normal business hours, access to the Contractor's 1-800 Video Testing Facilities, one business week on-site failed parts replacement, remote diagnostics and troubleshooting, and on-site problem resolution.
 Help Desk/Technical Center/Video Testing
 (800) 261-9008
 Remote Diagnostic and Troubleshooting
 (502) 657-2028
- f. **TRAVEL AND TRANSPORTATION.** If any charge is to apply over and above the regular maintenance rates, because of the distance between the ordering activity location and the Contractor's service area, the charge will be based upon Joint Travel Regulations and Federal Travel Regulations.
- g. **QUANTITY DISCOUNTS.** None.
- h. **MAINTENANCE RATE PROVISIONS FOR LEGACY SYSTEMS:** Maintenance for obsolete and legacy systems purchased from the Contractor and installed at Government facilities shall be priced at the rate of 20% of purchase price for plasma systems and 12% for nonplasma equipment.

9. REPAIR PARTS/SPARE PARTS RATE PROVISIONS

Repair service and repair parts/spare parts orders are not available under the scope of this contract.

10. GUARANTEE/WARRANTY—REPAIR SERVICE AND REPAIR PARTS/SPARE PARTS

Repair service and repair parts/spare parts orders are not available under the scope of this contract.

11. INVOICES AND PAYMENTS

a. Maintenance Service

- 1) Invoices for maintenance service shall be submitted by the Contractor on a quarterly or monthly basis, after the completion of such period. Maintenance charges must be paid in arrears (31 U.S.C. 3324). **PROMPT PAYMENT DISCOUNT, IF APPLICABLE, SHALL BE SHOWN ON THE INVOICE.**

- (2) Payment for maintenance service of less than one month's duration shall be prorated at 1/30th of the monthly rate for each calendar day.

b. Repair Service and Repair Parts/Spare Parts

Repair service and repair parts/spare parts orders are not available under the scope of this contract.

12. ANNUAL MAINTENANCE RENEWAL

Annual maintenance renewals will be subject to the current labor index Table 5 in accordance with the Department of Labor.

AUTHORIZED GSA SCHEDULE CONTRACT PRICING

Part Number	Description	GSA Price	Maintenace Price
TRI-2500	Armoire Credenza	\$4,025.03	\$531.30
TRI-3500	Executive Plasma Credenza A	\$30,220.45	\$3,989.10
TRI-3501	Executive Plasma Credenza B	\$27,197.91	\$3,590.12
TRI-3502	Executice Plasma Credenza C	\$34,250.52	\$4,521.07
TRI-3503	Executive Plasma Credenza D	\$37,273.07	\$4,920.05
TRI-3503-E	Executive Plasma Credenza E	\$40,295.62	\$5,319.02
TRI-4000	MobileEye Tactical Briefcase System A	\$30,220.45	\$3,989.10
TRI-4010	MobileEye Tactical Briefcase System B	\$35,258.04	\$4,654.06
TRI-5000	Front/Rear Projection VTC System A	\$60,440.91	\$7,978.20
TRI-5001	Front/Rear Projection VTC system B	\$56,410.84	\$7,446.23
TRI-5002	Front/Rear Projection VTC System C	\$55,403.33	\$7,313.24
TRI-5003	Front/Rear Projection VTC System D	\$50,365.74	\$6,648.28
TRI-5008	Dual 42" PlasmaPanel A	\$37,742.57	\$4,982.02
TRI-5009	Dual 42" PlasmaPanel B	\$36,678.63	\$4,841.58
TRI-5010	Dual 42" PlasmaPanel C	\$30,220.45	\$3,989.10
TRI-5011	Dual 42" PlasmaPanel D	\$24,168.30	\$3,190.22
TRI-5012	Dual 50" PlasmaPanel A	\$47,763.33	\$6,304.76
TRI-5013	Dual 50" PlasmaPanel B	\$46,299.41	\$6,111.52
TRI-5014	Dual 50" PlasmaPanel C	\$38,061.95	\$5,024.18
TRI-5015	Dual 50" PlasmaPanel D	\$34,156.82	\$4,508.70
TRI-5020	Single 42" PlasmaPanel A	\$29,727.78	\$3,924.07
TRI-5021	Single 42" PlasmaPanel B	\$28,160.08	\$3,717.13
TRI-5022	Single 42" PlasmaPanel C	\$22,173.42	\$2,926.89
TRI-5023	Single 42" PlasmaPanel D	\$17,532.80	\$2,314.33
TRI-5025	Single 50" PlasmaPanel A	\$39,791.86	\$5,252.53
TRI-5026	Single 50" PlasmaPanel B	\$37,949.11	\$5,009.28
TRI-5027	Single 50" PlasmaPanel C	\$32,235.49	\$4,255.08
TRI-5028	Single 50" PlasmaPanel D	\$27,554.57	\$3,637.20
TRI-7015	50" HDTV Plasma Flat Panel	\$10,074.16	\$1,329.79
TRI-7016	29" Video/VGA monitor	\$1,511.27	\$199.49
TRI-7017	36" TV Monitor	\$901.73	\$119.03
TRI-7018	Industrial VTC Monitor	\$3,022.55	\$398.98
TRI-7019	VTC Management Control System	\$4,533.82	\$598.46
TRI-7034	LCD -PLC Projector	\$6,548.86	\$864.45

Part Number	Description	GSA Price	Maintenace Price
TRI-7035	LCD Projector - 2200 ANSI Lumens	\$7,380.06	\$974.17
TRI-7036	LCD Projector - 3000 ANSI lumens	\$8,387.57	\$1,107.16
TRI-7037	CEILING MOUNT	\$755.64	\$99.74
TRI-7038	High-end RGB Projector	\$18,133.28	\$2,393.59
TRI-7039	Electronic Screen (6' x 8')	\$3,017.51	\$398.31
TRI-7042	DOCUMENT CAMERA A	\$3,017.51	\$398.31
TRI-7043	DOCUMENT CAMERA B	\$4,584.20	\$605.11
TRI-7044	DOCUMENT CAMERA C	\$5,037.58	\$664.96
TRI-7045	Scan Converter A	\$2,010.00	\$265.32
TRI-7046	Scan Converter B	\$4,528.79	\$597.80
TRI-7047	42" FLAT PANEL	\$5,425.48	\$716.16
TRI-7048	FLAT PANEL WALL MOUNT	\$302.25	\$39.90
TRI-7049	Audio AMPLIFIER	\$397.97	\$52.53
TRI-7050	Audio/video AMPLIFIER	\$498.72	\$65.83
TRI-7051	Input Switcher	\$604.51	\$79.80
TRI-7052	Speakers with Mount	\$302.25	\$39.90
TRI-7053	Black Box	\$503.76	\$66.50
TRI-7054	PTZ Camera A	\$1,606.99	\$212.12
TRI-7055	PTZ Camera B	\$3,017.51	\$398.31
TRI-7056	Microphones A	\$201.50	\$26.60
TRI-7057	Ceiling Microphones	\$226.69	\$29.92
TRI-7058	Push-to-Talk Microphones	\$302.25	\$39.90
TRI-7059	Microphones B	\$226.69	\$29.92
TRI-7060	CABLING & WIRING for VTC	\$503.76	\$66.50
TRI-7061	Audio System A	\$4,025.03	\$531.30
TRI-7062	Audio System B	\$6,040.06	\$797.29
TRI-7063	Upgrades for Audio System	\$1,209.02	\$159.59
TRI-7064	TSU/CSU	\$2,972.17	\$392.33
TRI-7065	Display Board	\$4,025.03	\$531.30
TRI-7068	Cabling & Wiring for room integration	\$3,526.31	\$465.47
TRI-7070	VCR A	\$79.59	\$10.51
TRI-7071	Slide Converter	\$4,433.07	\$585.17
TRI-7072	Rollabout Cabinet - Single monitor	\$906.76	\$119.69
TRI-7073	Rollabout Cabinet - Dual monitor	\$1,813.53	\$239.39
TRI-7074	DVD Player A	\$200.50	\$26.47
TRI-7075	INSTRUCTOR'S WORKSTATION	\$6,040.06	\$797.29
TRI-7077	Touch Screen	\$4,584.20	\$605.11

Part Number	Description	GSA Price	Maintenance Price
TRI-7078	Scan Doubler	\$7,556.37	\$997.44
TRI-7079	Switch and Cables	\$806.01	\$106.39
TRI-7101	ISU 128	\$780.83	\$103.07
TRI-7102	Rack mount rails	\$100.75	\$13.30
TRI-7104	Audio System C	\$1,209.02	\$159.59
TRI-7106	13"TV/VCR Combo	\$332.43	\$43.88
TRI-7107	20" TV/VCR Combo	\$453.33	\$59.84
TRI-7108	27"Monitor/Receiver	\$800.98	\$105.73
TRI-7109	32" Monitor/Receiver	\$1,002.48	\$132.33
TRI-7110	36" Monitor/Receiver	\$1,606.99	\$212.12
TRI-7115	ISU 512	\$3,525.30	\$465.34
TRI-7116	ISU 2 x 64 (U Interface)	\$1,006.51	\$132.86
TRI-7123	Collaboration System	\$705.26	\$93.09
TRI-7202	Wide-angle camera	\$1,808.49	\$238.72
TRI-7204	17" monitor Desktop PC	\$2,417.03	\$319.05
TRI-7205	Touch Screen & Stand	\$4,025.03	\$531.30
TRI-7207	32" Dual Monitor Stand	\$1,813.53	\$239.39
TRI-7208	36" Dual Monitor Stand	\$2,115.78	\$279.28
TRI-7209	50" Dual Plasma Stand	\$3,123.30	\$412.28
TRI-7210	NT-1 ISDN CONNECTORS	\$201.50	\$26.60
TRI-7211	NT-3 ISDN CONNECTORS	\$403.01	\$53.20
TRI-7212	NT-4 ISDN CONNECTORS	\$604.51	\$79.80
TRI-7215	42" Plasma Screen (16x9)	\$9,062.61	\$1,196.26
TRI-7216	50" Plasma Screen (16x9)	\$13,601.47	\$1,795.39
TRI-7217	Front Projection Screen	\$2,821.05	\$372.38
TRI-7218	27" Monitor	\$800.98	\$105.73
TRI-7219	36" Monitor	\$1,511.27	\$199.49
TRI-7220	Industrial VGA Monitor	\$3,022.55	\$398.98
TRI-7221	Scan converter	\$2,010.00	\$265.32
TRI-7223	High-end Multi Input Switcher	\$4,025.03	\$531.30
TRI-7224	Equipment rack	\$1,209.02	\$159.59
TRI-7228	Fast Ethernet Converter	\$250.87	\$33.11
TRI-7230	Converter	\$4,533.82	\$598.46
TRI-8030	Front Projection	\$5,037.58	\$664.96
TRI-9001	Tactical Codec System A	\$30,215.42	\$3,988.44
TRI-9002	Tactical Codec System B	\$36,270.59	\$4,787.72
TRI-9006	Codec BA	\$6,519.69	\$782.36

Part Number	Description	GSA Price	Maintenance Price
TRI-9007	Codec BC	\$5,588.19	\$670.58
TRI-9008	Codec BD	\$4,656.69	\$558.80
TRI-9009	Codec BE	\$3,303.99	\$396.48
TRI-9013	Codec Upgrade A	\$659.92	\$87.11
TRI-9014	Codec E	\$12,233.26	\$1,614.79
TRI-9015	Codec F	\$9,785.00	\$1,291.62
TRI-9016	Codec AZ	\$7,451.19	\$894.14
TRI-9017	Codec H	\$12,233.26	\$1,614.79
TRI-9018	Codec BJ	\$8,712.00	\$1,045.44
TRI-9019	Codec BB	\$6,519.69	\$782.36
TRI-9024	Codec System A	\$4,480.43	\$591.42
TRI-9025	Codec System DC	\$2,418.36	\$290.20
TRI-9026	Codec System DE	\$4,860.00	\$860.73
TRI-9027	Codec System DK	\$6,952.00	\$834.24
TRI-9032	Codec K	\$17,129.79	\$2,261.13
TRI-9033	Codec System CX	\$15,834.69	\$1,900.16
TRI-9034	Codec System CY	\$13,971.69	\$1,676.60
TRI-9035	Codec System G	\$20,394.15	\$2,692.03
TRI-9036	Codec System DB	\$9,314.19	\$1,117.70
TRI-9037	Codec System CZ	\$12,108.69	\$1,453.04
TRI-9038	Codec System DA	\$12,108.69	\$1,453.04
TRI-9039	Codec System K	\$17,945.88	\$2,368.86
TRI-9040	Codec System DG	\$7,290.00	\$1,722.51
TRI-9041	Codec System DJ	\$7,290.00	\$1,830.24
TRI-9042	Codec System N	\$13,865.44	\$1,830.24
TRI-9043	Codec System O	\$16,313.71	\$2,153.41
TRI-9044	Codec Portable System A	\$16,313.71	\$2,153.41
TRI-9045	Codec Portable System B	\$13,865.44	\$1,830.24
TRI-9046	Codec Portable System C	\$12,233.26	\$1,614.79
TRI-9047	Codec L	\$15,497.62	\$2,045.69
TRI-9048	Codec M	\$13,049.35	\$1,722.51
TRI-9049	Codec N	\$11,417.18	\$1,507.07
TRI-9063	Codec System P	\$24,474.59	\$3,230.65
TRI-9064	Codec System Q	\$26,514.81	\$3,499.95
TRI-9065	Codec System R	\$21,210.24	\$2,799.75
TRI-9066	Codec System S	\$23,250.46	\$3,069.06
TRI-9067	Codec System T	\$19,578.06	\$2,584.30

Part Number	Description	GSA Price	Maintenance Price
TRI-9068	Codec System U	\$21,618.28	\$2,853.61
TRI-9069	Codec System V	\$28,146.99	\$3,715.40
TRI-9070	Codec System W	\$26,106.76	\$3,446.09
TRI-9071	Codec System DH	\$23,672.00	\$2,840.64
TRI-9072	Codec System Y	\$22,842.41	\$3,015.20
TRI-9073	Codec System Z	\$23,250.46	\$3,069.06
TRI-9074	Codec System AA	\$21,210.24	\$2,799.75
TRI-9075	Codec Portable System D	\$22,434.37	\$2,961.34
TRI-9076	Codec Portable System E	\$19,170.01	\$2,530.44
TRI-9077	Codec Portable System F	\$17,537.84	\$2,314.99
TRI-9078	Codec Portable System G	\$24,066.54	\$3,176.78
TRI-9079	Codec Portable System H	\$20,802.19	\$2,745.89
TRI-9080	Codec Portable System I	\$19,170.01	\$2,530.44
TRI-9081	Codec O	\$22,026.32	\$2,907.47
TRI-9082	Codec BH	\$16,632.00	\$1,995.84
TRI-9083	Codec BF	\$12,232.00	\$1,467.84
TRI-9084	Codec R	\$23,658.50	\$3,122.92
TRI-9085	Codec BG	\$19,272.00	\$2,312.64
TRI-9086	Codec BI	\$14,872.00	\$1,784.64
TRI-9100	Codec System DF	\$28,952.00	\$3,474.24
TRI-9101	Codec System CW	\$46,574.19	\$5,588.90
TRI-9105	Management System A	\$1,237.23	\$163.31
TRI-9106	Management System B	\$6,184.14	\$816.31
TRI-9107	Management System C	\$12,368.27	\$1,632.61
TRI-9108	Management System D	\$24,736.54	\$3,265.22
TRI-9109	Management System E	\$36,074.12	\$4,761.78
TRI-9115	MCU A	\$40,796.35	\$5,385.12
TRI-9116	MCU B	\$57,118.12	\$7,539.59
TRI-9120	MCU Accessory A	\$9,360.83	\$1,235.63
TRI-9122	Codec Upgrade BU	\$1,133.19	\$135.98
TRI-9123	Codec Upgrade BV	\$3,887.19	\$466.46
TRI-9124	Codec Upgrade BX	\$1,620.00	\$323.17
TRI-9125	Codec Upgrade BW	\$2,915.19	\$349.82
TRI-9126	Codec Upgrade CE	\$2,430.00	\$323.17
TRI-9127	Codec Upgrade BZ	\$2,430.00	\$430.89
TRI-9128	Codec Upgrade H	\$1,224.13	\$161.59
TRI-9129	Codec Upgrade I	\$1,224.13	\$161.59

Part Number	Description	GSA Price	Maintenance Price
TRI-9130	MCU Upgrade A	\$24,482.65	\$3,231.71
TRI-9131	Codec Upgrade CH	\$2,430.00	\$323.17
TRI-9132	Codec Upgrade BY	\$3,240.00	\$495.53
TRI-9133	Codec Upgrade CC	\$1,620.00	\$247.76
TRI-9134	Codec Upgrade CF	\$1,620.00	\$247.76
TRI-9135	Codec Upgrade CK	\$1,620.00	\$247.76
TRI-9136	Codec Upgrade CN	\$1,620.00	\$247.76
TRI-9137	Codec Upgrade CA	\$3,240.00	\$495.53
TRI-9138	Codec Upgrade Q	\$1,265.44	\$167.04
TRI-9145	Management System	\$10,070.13	\$1,329.26
TRI-9150	PTZ Camera C	\$3,420.52	\$451.51
TRI-9200	Document Camera D	\$2,098.15	\$276.96
TRI-9201	Codec BK	\$3,239.19	\$388.70
TRI-9203	Codec V	\$13,012.91	\$1,717.70
TRI-9204	Codec W	\$5,456.54	\$720.26
TRI-9205	Codec X	\$7,974.49	\$1,052.63
TRI-9206	Codec Y	\$13,012.91	\$1,717.70
TRI-9207	Codec Z	\$1,678.35	\$221.54
TRI-9208	Codec AA	\$3,357.55	\$443.20
TRI-9209	Codec AB	\$5,036.74	\$664.85
TRI-9210	Codec AC	\$3,525.47	\$465.36
TRI-9211	Codec AD	\$10,074.32	\$1,329.81
TRI-9212	Codec AE	\$5,288.62	\$698.10
TRI-9213	Codec AF	\$5,288.62	\$698.10
TRI-9214	Codec AG	\$1,678.35	\$221.54
TRI-9215	Codec AH	\$2,517.95	\$332.37
TRI-9216	MCU C	\$18,471.13	\$2,438.19
TRI-9217	MCU D	\$28,966.10	\$3,823.53
TRI-9218	MCU E	\$22,669.12	\$2,992.32
TRI-9219	MCU F	\$31,904.69	\$4,211.42
TRI-9220	MCU G	\$53,314.41	\$7,037.50
TRI-9221	MCU H	\$21,829.52	\$2,881.50
TRI-9222	MCU I	\$36,522.47	\$4,820.97
TRI-9223	MCU J	\$53,314.41	\$7,037.50
TRI-9224	MCU K	\$50,333.84	\$6,644.07
TRI-9225	MCU L	\$67,125.78	\$8,860.60
TRI-9226	MCU Upgrade B	\$36,060.69	\$4,760.01

Part Number	Description	GSA Price	Maintenance Price
TRI-9227	MCU Upgrade C	\$25,565.73	\$3,374.68
TRI-9228	MCU Upgrade D	\$18,009.36	\$2,377.24
TRI-9229	MCU Upgrade E	\$32,702.30	\$4,316.70
TRI-9230	MCU Upgrade F	\$18,009.36	\$2,377.24
TRI-9231	MCU Upgrade G	\$18,009.36	\$2,377.24
TRI-9232	MCU Upgrade H	\$31,862.71	\$4,205.88
TRI-9233	MCU Upgrade I	\$13,433.55	\$1,773.23
TRI-9234	MCU M	\$127,870.62	\$16,878.92
TRI-9235	MCU N	\$176,063.49	\$23,240.38
TRI-9236	MCU O	\$238,361.59	\$31,463.73
TRI-9237	MCU P	\$441,208.22	\$58,239.49
TRI-9238	MCU Q	\$52,894.61	\$6,982.09
TRI-9239	MCU R	\$76,319.37	\$10,074.16
TRI-9243	MCU Accessory E	\$251.88	\$33.25
TRI-9246	MCU Accessory H	\$3,358.39	\$443.31
TRI-9248	MCU Accessory J	\$4,197.98	\$554.13
TRI-9249	MCU Accessory K	\$4,197.98	\$554.13
TRI-9250	MCU S	\$14,692.95	\$1,939.47
TRI-9251	MCU T	\$4,617.78	\$609.55
TRI-9252	MCU U	\$22,081.40	\$2,914.74
TRI-9253	MCU V	\$8,647.85	\$1,141.52
TRI-9254	MCU W	\$22,921.00	\$3,025.57
TRI-9255	MCU X	\$8,647.85	\$1,141.52
TRI-9256	MCU Y	\$43,910.92	\$5,796.24
TRI-9257	MCU Z	\$29,637.77	\$3,912.19
TRI-9258	MCU AA	\$10,075.16	\$1,329.92
TRI-9259	MCU AB	\$10,075.16	\$1,329.92
TRI-9260	MCU Accessory L	\$41.98	\$5.54
TRI-9261	MCU Accessory M	\$54.57	\$7.20
TRI-9262	MCU AC	\$5,037.58	\$664.96
TRI-9263	MCU AD	\$5,037.58	\$664.96
TRI-9264	MCU AE	\$10,075.16	\$1,329.92
TRI-9265	MCU AF	\$10,075.16	\$1,329.92
TRI-9266	MCU AG	\$7,052.61	\$930.94
TRI-9267	MCU AH	\$13,433.55	\$1,773.23
TRI-9268	MCU AI	\$23,508.72	\$3,103.15
TRI-9269	MCU AJ	\$12,593.95	\$1,662.40

Part Number	Description	GSA Price	Maintenance Price
TRI-9270	MCU AK	\$24,348.31	\$3,213.98
TRI-9271	MCU AL	\$41,140.25	\$5,430.51
TRI-9272	MCU AM	\$9,151.61	\$1,208.01
TRI-9273	MCU AN	\$14,273.15	\$1,884.06
TRI-9274	MCU Upgrade J	\$5,121.54	\$676.04
TRI-9275	MCU AO	\$13,181.67	\$1,739.98
TRI-9276	MCU AP	\$13,181.67	\$1,739.98
TRI-9277	MCU AQ	\$24,768.11	\$3,269.39
TRI-9278	MCU AR	\$38,117.70	\$5,031.54
TRI-9279	MCU AS	\$7,808.25	\$1,030.69
TRI-9280	MCU AT	\$12,132.18	\$1,601.45
TRI-9281	MCU AU	\$15,112.75	\$1,994.88
TRI-9282	MCU AV	\$23,508.72	\$3,103.15
TRI-9283	MCU AW	\$30,225.49	\$3,989.76
TRI-9284	MCU Accessory N	\$377.82	\$49.87
TRI-9285	MCU Accessory O	\$11,334.56	\$1,496.16
TRI-9286	MCU Accessory P	\$17,631.54	\$2,327.36
TRI-9287	MCU Accessory Q	\$4,197.98	\$554.13
TRI-9288	MCU Accessory R	\$8,395.97	\$1,108.27
TRI-9289	MCU Accessory S	\$6,296.98	\$831.20
TRI-9290	MCU Accessory T	\$4,197.98	\$554.13
TRI-9291	MCU Accessory U	\$25,187.91	\$3,324.80
TRI-9292	MCU Accessory V	\$54,573.80	\$7,203.74
TRI-9293	MCU Accessory W	\$62,969.77	\$8,312.01
TRI-9294	MCU Accessory X	\$8,395.97	\$1,108.27
TRI-9295	MCU Accessory Y	\$12,593.95	\$1,662.40
TRI-9296	MCU Accessory Z	\$696.87	\$91.99
TRI-9297	MCU Accessory AA	\$839.60	\$110.83
TRI-9298	MCU Accessory AB	\$4,197.98	\$554.13
TRI-9299	MCU Upgrade K	\$12,593.95	\$1,662.40
TRI-9300	MCU Accessory AC	\$12,593.95	\$1,662.40
TRI-9301	MCU Accessory AD	\$18,890.93	\$2,493.60
TRI-9302	MCU Accessory AE	\$28,336.40	\$3,740.40
TRI-9303	MCU Accessory AF	\$50,921.56	\$6,721.65
TRI-9304	MCU Accessory AG	\$63,809.37	\$8,422.84
TRI-9305	MCU Accessory AH	\$20,989.92	\$2,770.67
TRI-9306	MCU Accessory AI	\$8,395.97	\$1,108.27

Part Number	Description	GSA Price	Maintenance Price
TRI-9307	MCU Accessory AJ	\$12,593.95	\$1,662.40
TRI-9308	MCU Accessory AK	\$6,506.88	\$858.91
TRI-9309	MCU Accessory AL	\$6,716.78	\$886.61
TRI-9310	MCU Accessory AM	\$2,518.79	\$332.48
TRI-9311	MCU Accessory AN	\$5,037.58	\$664.96
TRI-9312	MCU Accessory AO	\$12,593.95	\$1,662.40
TRI-9313	MCU Accessory AP	\$24,810.09	\$3,274.93
TRI-9314	MCU Accessory AQ	\$36,665.20	\$4,839.81
TRI-9315	MCU Accessory AR	\$48,469.93	\$6,398.03
TRI-9316	MCU Accessory AS	\$59,325.92	\$7,831.02
TRI-9317	MCU Accessory AT	\$70,156.73	\$9,260.69
TRI-9318	MCU Accessory AU	\$80,668.48	\$10,648.24
TRI-9319	MCU Accessory AV	\$90,869.58	\$11,994.78
TRI-9320	MCU Accessory AW	\$100,768.43	\$13,301.43
TRI-9321	MCU Accessory AX	\$110,373.42	\$14,569.29
TRI-9322	MCU Accessory AY	\$119,692.95	\$15,799.47
TRI-9323	MCU Accessory AZ	\$128,735.41	\$16,993.07
TRI-9324	MCU Accessory BA	\$137,484.01	\$18,147.89
TRI-9325	MCU Accessory BB	\$146,022.71	\$19,275.00
TRI-9326	MCU Accessory BC	\$154,284.34	\$20,365.53
TRI-9327	MCU Accessory BD	\$162,302.50	\$21,423.93
TRI-9328	MCU Accessory BE	\$170,085.56	\$22,451.29
TRI-9329	MCU Accessory BF	\$177,641.93	\$23,448.73
TRI-9330	MCU Accessory BG	\$184,971.61	\$24,416.25
TRI-9331	MCU Accessory BH	\$192,083.00	\$25,354.96
TRI-9332	MCU Accessory BI	\$4,197.15	\$554.02
TRI-9333	MCU Accessory BJ	\$16,791.10	\$2,216.43
TRI-9334	MCU Accessory BK	\$50,374.98	\$6,649.50
TRI-9335	MCU Accessory BL	\$125,938.71	\$16,623.91
TRI-9336	MCU Accessory BM	\$4,197.15	\$554.02
TRI-9337	MCU Accessory BN	\$16,791.10	\$2,216.43
TRI-9338	MCU Accessory BO	\$50,374.98	\$6,649.50
TRI-9339	MCU Accessory BP	\$125,938.71	\$16,623.91
TRI-9340	MCU Accessory BQ	\$838.76	\$110.72
TRI-9341	MCU Accessory BR	\$3,357.55	\$443.20
TRI-9342	MCU Accessory BS	\$10,074.32	\$1,329.81
TRI-9343	MCU Accessory BT	\$25,187.07	\$3,324.69

Part Number	Description	GSA Price	Maintenance Price
TRI-9344	MCU Accessory BU	\$6,296.14	\$831.09
TRI-9345	MCU Accessory BV	\$25,187.07	\$3,324.69
TRI-9346	MCU Accessory BW	\$75,562.89	\$9,974.30
TRI-9347	MCU Accessory BX	\$188,908.48	\$24,935.92
TRI-9348	MCU Accessory BY	\$6,296.14	\$831.09
TRI-9349	MCU Accessory BZ	\$25,187.07	\$3,324.69
TRI-9350	MCU Accessory CA	\$75,562.89	\$9,974.30
TRI-9351	MCU Accessory CB	\$188,908.48	\$24,935.92
TRI-9352	MCU Accessory CC	\$1,258.56	\$166.13
TRI-9353	MCU Accessory CD	\$5,036.74	\$664.85
TRI-9354	MCU Accessory CE	\$15,111.91	\$1,994.77
TRI-9355	MCU Accessory CF	\$37,781.03	\$4,987.10
TRI-9356	MCU Accessory CG	\$18,890.09	\$2,493.49
TRI-9357	MCU Accessory CH	\$52,893.77	\$6,981.98
TRI-9358	MCU Accessory CI	\$2,517.95	\$332.37
TRI-9359	MCU Accessory CJ	\$10,074.32	\$1,329.81
TRI-9360	MCU Accessory CK	\$30,224.65	\$3,989.65
TRI-9361	MCU Accessory CL	\$75,562.89	\$9,974.30
TRI-9362	MCU Accessory CM	\$9,234.73	\$1,218.98
TRI-9363	MCU Accessory CN	\$36,101.83	\$4,765.44
TRI-9364	MCU Accessory CO	\$109,146.77	\$14,407.37
TRI-9365	MCU Accessory CP	\$272,868.18	\$36,018.60
TRI-9366	MCU Accessory CQ	\$9,234.73	\$1,218.98
TRI-9367	MCU Accessory CR	\$36,101.83	\$4,765.44
TRI-9368	MCU Accessory CS	\$109,146.77	\$14,407.37
TRI-9369	MCU Accessory CT	\$272,868.18	\$36,018.60
TRI-9370	MCU Accessory CU	\$1,846.27	\$243.71
TRI-9371	MCU Accessory CV	\$7,219.69	\$953.00
TRI-9372	MCU Accessory CW	\$21,828.68	\$2,881.39
TRI-9373	MCU Accessory CX	\$54,572.97	\$7,203.63
TRI-9374	MCU Accessory CY	\$1,048.66	\$138.42
TRI-9375	MCU Accessory CZ	\$2,098.15	\$276.96
TRI-9376	MCU Accessory DA	\$5,246.64	\$692.56
TRI-9377	MCU Accessory DB	\$10,494.12	\$1,385.22
TRI-9378	MCU Accessory DC	\$4,197.15	\$554.02
TRI-9379	MCU Accessory DD	\$8,395.13	\$1,108.16
TRI-9380	MCU Accessory DE	\$20,989.09	\$2,770.56

Part Number	Description	GSA Price	Maintenace Price
TRI-9381	MCU Accessory DF	\$41,979.01	\$5,541.23
TRI-9382	Management System F	\$209.06	\$27.60
TRI-9383	Management System G	\$1,006.68	\$132.88
TRI-9384	Management System H	\$4,197.15	\$554.02
TRI-9385	Management System I	\$8,395.13	\$1,108.16
TRI-9386	Management System J	\$20,989.09	\$2,770.56
TRI-9387	Management System K	\$41,979.01	\$5,541.23
TRI-9388	Custom Room G	\$100,751.64	\$13,299.22
TRI-9389	Custom Room H	\$201,503.28	\$26,598.43
TRI-9390	Custom Room I	\$302,254.92	\$39,897.65
TRI-9391	Custom Room J	\$403,006.56	\$53,196.87
TRI-9392	Custom Room K	\$503,758.20	\$66,496.08
TRI-9393	Custom Room L	\$604,509.84	\$79,795.30
TRI-9394	Custom Room M	\$705,261.48	\$93,094.52
TRI-9395	Custom Room N	\$806,013.12	\$106,393.73
TRI-9396	Custom Room O	\$906,764.76	\$119,692.95
TRI-9397	Custom Room P	\$1,007,516.40	\$132,992.16
TRI-9398	Tactical Codec System C	\$35,258.04	\$4,654.06
TRI-9399	Tactical Codec System D	\$30,220.45	\$3,989.10
TRI-9400	Tactical Codec System E	\$39,288.10	\$5,186.03
TRI-9401	Tactical Codec System F	\$34,250.52	\$4,521.07
TRI-9402	Set of High Fidelity Speakers	\$498.72	\$65.83
TRI-9403	15" LCD's	\$704.25	\$92.96
TRI-9405	15" Rack mounted LCD	\$2,987.29	\$394.32
TRI-9407	ISU 2x64	\$1,304.73	\$172.22
TRI-9408	Codec Upgrade CB	\$3,240.00	\$430.89
TRI-9409	Cabling for KIV7	\$99.74	\$13.17
TRI-9411	Codec Upgrade CD	\$3,240.00	\$538.62
TRI-9412	PTZ Camera D with 50' Cable	\$3,454.77	\$456.03
TRI-9413	Voice Activated Camera positioning microphone	\$553.13	\$73.01
TRI-9414	Daisy Chain Control Cable 50'	\$261.95	\$34.58
TRI-9416	MCU AX	\$325,225.29	\$42,929.74
TRI-9417	MCU AY	\$156,165.04	\$20,613.79
TRI-9418	MCU AZ	\$168,804.33	\$22,282.17
TRI-9419	MCU BA	\$180,129.83	\$23,777.14
TRI-9422	MCU Accessory DG	\$15,112.75	\$1,994.88
TRI-9423	MCU Accessory DH	\$1,478.03	\$195.10

Part Number	Description	GSA Price	Maintenance Price
TRI-9427	Demo MCU	\$108,574.00	\$14,331.77
TRI-9428	Tactical Codec System G	\$24,721.43	\$3,263.23
TRI-9429	PTZ Camera E	\$2,737.42	\$361.34
TRI-9430	PTZ Camera F with 2m S-Video Cable	\$112.84	\$14.89
TRI-9431	PTZ Camera Power Supply	\$150.94	\$19.92
TRI-9432	RS449/366 6000 cable	\$281.30	\$37.13
TRI-9435	Engineering for cabling configurations	\$587.38	\$77.53
TRI-9437	Trinity Secure Software Management System	\$6,901.49	\$911.00
TRI-9438	IBM Compatible PC & Accessories	\$2,971.17	\$392.19
TRI-9439	15" Color Graphics Touch Screen with Stand	\$2,463.38	\$325.17
TRI-9445	Codec System AD	\$50,367.42	\$6,648.50
TRI-9446	Codec System DI	\$33,352.00	\$4,002.24
TRI-9447	Codec System AF	\$25,431.39	\$3,356.94
TRI-9448	Codec System AG	\$21,737.17	\$2,869.31
TRI-9449	Codec System AH	\$22,240.92	\$2,935.80
TRI-9450	Codec System AI	\$20,141.93	\$2,658.73
TRI-9451	Codec Upgrade T	\$1,679.19	\$201.50
TRI-9452	Codec Upgrade CG	\$3,240.00	\$403.01
TRI-9453	Codec Upgrade V	\$1,679.19	\$201.50
TRI-9454	Codec System AJ	\$21,401.33	\$2,568.16
TRI-9455	Codec Upgrade W	\$1,679.19	\$201.50
TRI-9456	Codec Upgrade CI	\$3,240.00	\$403.01
TRI-9457	Codec Upgrade Y	\$1,679.19	\$201.50
TRI-9458	Codec System AK	\$16,279.79	\$2,148.93
TRI-9459	Codec System AL	\$14,432.67	\$1,905.11
TRI-9460	Codec System AM	\$14,264.75	\$1,882.95
TRI-9461	Codec System AN	\$13,425.16	\$1,772.12
TRI-9462	Codec Upgrade Z	\$1,679.19	\$201.50
TRI-9463	Codec Upgrade CL	\$2,430.00	\$302.25
TRI-9464	Codec Upgrade CM	\$2,430.00	\$302.25
TRI-9465	PTZ Camera N	\$5,264.19	\$805.01
TRI-9466	PTZ Camera O	\$5,264.19	\$704.25
TRI-9467	Codec System AQ	\$5,029.19	\$603.50
TRI-9468	Codec System AR	\$10,066.77	\$1,328.81
TRI-9469	Codec Upgrade AC	\$1,679.19	\$201.50
TRI-9470	Codec Upgrade AD	\$2,518.79	\$302.25
TRI-9471	Codec Upgrade AE	\$1,679.19	\$201.50

Part Number	Description	GSA Price	Maintenance Price
TRI-9472	Codec System AS	\$5,448.98	\$653.88
TRI-9473	Codec Upgrade AF	\$1,679.19	\$201.50
TRI-9474	Codec Upgrade AG	\$2,518.79	\$302.25
TRI-9475	Codec Upgrade AH	\$1,679.19	\$201.50
TRI-9476	Codec Upgrade AI	\$839.60	\$100.75
TRI-9477	Codec System AT	\$7,547.98	\$905.76
TRI-9478	Codec Upgrade AJ	\$1,679.19	\$201.50
TRI-9479	Codec Upgrade AK	\$2,518.79	\$302.25
TRI-9480	Codec Upgrade AL	\$1,679.19	\$201.50
TRI-9481	Codec System AU	\$6,708.38	\$805.01
TRI-9482	Codec Upgrade AM	\$1,679.19	\$201.50
TRI-9483	Codec Upgrade AN	\$2,518.79	\$302.25
TRI-9484	Codec Upgrade AO	\$1,679.19	\$201.50
TRI-9485	Codec System AV	\$5,868.78	\$704.25
TRI-9486	Codec Upgrade AP	\$1,679.19	\$201.50
TRI-9487	Codec Upgrade AQ	\$839.60	\$100.75
TRI-9488	Codec System AW	\$5,029.19	\$603.50
TRI-9489	Codec System AX	\$4,189.59	\$502.75
TRI-9490	Codec Upgrade AR	\$839.60	\$100.75
TRI-9491	Codec System AY	\$16,783.54	\$2,014.02
TRI-9492	Codec Upgrade AS	\$1,679.19	\$201.50
TRI-9493	Codec Upgrade CJ	\$3,240.00	\$403.01
TRI-9494	Codec Upgrade AU	\$1,679.19	\$201.50
TRI-9495	Codec Upgrade AV	\$3,358.39	\$403.01
TRI-9496	Codec System AZ	\$12,585.56	\$1,510.27
TRI-9497	Codec Upgrade AW	\$1,679.19	\$201.50
TRI-9498	Codec Upgrade AX	\$2,518.79	\$302.25
TRI-9499	Codec Upgrade AY	\$2,518.79	\$302.25
TRI-9500	Codec System BA	\$15,943.95	\$1,913.27
TRI-9501	Codec Upgrade AZ	\$1,679.19	\$201.50
TRI-9502	Codec Upgrade BA	\$3,358.39	\$403.01
TRI-9503	Codec Upgrade BB	\$1,679.19	\$201.50
TRI-9504	Codec Upgrade BC	\$3,358.39	\$403.01
TRI-9505	Codec System BB	\$11,745.96	\$1,409.52
TRI-9506	Codec Upgrade BD	\$1,679.19	\$201.50
TRI-9507	Codec Upgrade BE	\$2,518.79	\$302.25
TRI-9508	Codec Upgrade BF	\$2,518.79	\$302.25

Part Number	Description	GSA Price	Maintenace Price
TRI-9509	Codec Carrying Case	\$418.96	\$50.28
TRI-9510	Codec AI	\$4,197.15	\$503.66
TRI-9511	Codec AJ	\$5,456.54	\$654.78
TRI-9512	Codec AK	\$10,913.92	\$1,309.67
TRI-9513	Custom Room Q	\$1,511,274.60	\$199,488.25
TRI-9514	Custom Room R	\$2,015,032.80	\$265,984.33
TRI-9515	Custom Room S	\$2,518,790.99	\$332,480.41
TRI-9516	Custom Room T	\$3,022,549.19	\$398,976.49
TRI-9517	Custom Room U	\$3,526,307.39	\$465,472.58
TRI-9518	Custom Room V	\$4,030,065.59	\$531,968.66
TRI-9519	Custom Room W	\$4,533,823.79	\$598,464.74
TRI-9520	Custom Room X	\$5,037,581.99	\$664,960.82
TRI-9521	Codec AL	\$2,510.40	\$331.37
TRI-9522	Codec AM	\$15,111.91	\$1,994.77
TRI-9523	Codec AN	\$11,753.52	\$1,551.46
TRI-9524	Codec Network Module A	\$1,258.56	\$166.13
TRI-9525	Codec Network Module B	\$2,517.95	\$332.37
TRI-9526	Codec Network Module C	\$1,258.56	\$166.13
TRI-9527	Codec Upgrade BG	\$2,517.95	\$332.37
TRI-9528	Codec Upgrade BH	\$754.80	\$99.63
TRI-9529	PTZ Camera G	\$1,258.56	\$166.13
TRI-9530	PTZ Camera H	\$1,258.56	\$166.13
TRI-9531	PTZ Camera I	\$2,517.95	\$332.37
TRI-9532	PTZ Camera J	\$1,258.56	\$166.13
TRI-9533	Codec AO	\$9,654.53	\$1,274.40
TRI-9534	Codec AP	\$6,715.94	\$886.50
TRI-9535	Codec Network Module D	\$1,258.56	\$166.13
TRI-9536	Codec Network Module E	\$2,517.95	\$332.37
TRI-9537	Codec Network Module F	\$1,258.56	\$166.13
TRI-9538	PTZ Camera K	\$1,258.56	\$166.13
TRI-9539	Codec AQ	\$4,197.15	\$554.02
TRI-9540	Codec AR	\$1,678.35	\$221.54
TRI-9541	Codec AS	\$2,517.95	\$332.37
TRI-9542	Codec AT	\$2,098.15	\$276.96
TRI-9543	Codec AU	\$2,937.75	\$387.78
TRI-9544	Custom Room Y	\$50,375.82	\$6,649.61
TRI-9545	Custom Room Z	\$151,127.46	\$19,948.82

Part Number	Description	GSA Price	Maintenance Price
TRI-9546	Custom Room AA	\$251,879.10	\$33,248.04
TRI-9547	Custom Room AB	\$352,630.74	\$46,547.26
TRI-9548	Custom Room AC	\$453,382.38	\$59,846.47
TRI-9549	Custom Room AD	\$554,134.02	\$73,145.69
TRI-9550	Custom Room AE	\$654,885.66	\$86,444.91
TRI-9551	Custom Room AF	\$755,637.30	\$99,744.12
TRI-9552	Custom Room AG	\$856,388.94	\$113,043.34
TRI-9553	Custom Room AH	\$957,140.58	\$126,342.56
TRI-9554	50" Flat Panel A*	\$7,556.37	\$1,511.27
TRI-9555	LCD A*	\$5,037.58	\$604.51
TRI-9556	LCD B*	\$10,075.16	\$1,209.02
TRI-9557	Dual Plasma T-stand A*	\$50,371.62	\$6,649.05
TRI-9558	Dual Plasma T-stand B*	\$59,439.27	\$7,845.98
TRI-9559	Dual Plasma T-stand C*	\$70,521.95	\$9,308.90
TRI-9560	DVD Recorder	\$1,523.03	\$182.76
TRI-9561	User Manuals	\$2,010.83	\$241.30
TRI-9562	Network Controller	\$9,235.57	\$1,108.27
TRI-9563	Network Controller Upgrade A	\$5,037.58	\$604.51
TRI-9564	Network Controller Upgrade B	\$10,075.16	\$1,209.02
TRI-9565	Mobile Responder including codec, integrated camera, speaker, microphone, 17" LCD monitor, presenter package, remote, wheels, & pullout handle	\$17,930.43	\$2,366.82
TRI-9566	Codec Upgrade BI	\$3,827.72	\$459.33
TRI-9567	Codec Upgrade BJ	\$477.73	\$57.33
TRI-9568	Codec Upgrade BK	\$477.73	\$57.33
TRI-9569	Codec Upgrade BL	\$2,517.95	\$332.37
TRI-9570	Codec Upgrade BM	\$754.80	\$99.63
TRI-9571	Codec AV	\$3,357.55	\$443.20
TRI-9572	Codec AW	\$5,035.90	\$664.74
TRI-9573	Codec AX	\$3,777.35	\$498.61
TRI-9574	Codec AY	\$5,456.54	\$720.26
TRI-9580	PC VTC Unit F	\$150.13	\$19.82
TRI-9581	PC VTC Unit G	\$5,994.96	\$791.33
TRI-9582	PC VTC Unit H	\$10,982.37	\$1,449.67
TRI-9583	PC VTC Unit I	\$19,949.62	\$2,633.35
TRI-9584	PC VTC Unit J	\$44,836.27	\$5,918.39

Part Number	Description	GSA Price	Maintenace Price
TRI-9585	PC VTC Unit K	\$65,491.19	\$8,644.84
TRI-9586	PC VTC Unit L	\$246,851.39	\$32,584.38
TRI-9587	PC VTC Unit M	\$150.13	\$19.82
TRI-9588	PC VTC Unit N	\$300.25	\$39.63
TRI-9589	Large Flat Panel Display*	\$18,135.01	\$2,393.82
TRI-9590	Large Flat Panel Display Wall Mount*	\$704.28	\$92.96
TRI-9591	Trinity's Secure Multi-Media Communications Systems*	\$50,363.73	\$6,648.01
TRI-9592	Trinity's Secure touch screen access control software interface,including hardware, GUI and software license fee.	\$15,112.34	\$1,994.83
TRI-9594	Codec CU	\$18,629.19	\$2,459.05
TRI-9595	Codec System BA	\$11,339.19	\$1,496.77
TRI-9596	Codec System BB	\$16,199.19	\$2,138.29
TRI-9597	Codec System BC	\$12,959.19	\$1,710.61
TRI-9598	Codec System BD	\$17,819.19	\$2,352.13
TRI-9599	Codec System CV	\$20,249.19	\$2,672.89
TRI-9600	Codec System BF	\$16,199.19	\$2,138.29
TRI-9601	Codec Upgrade BN	\$4,859.19	\$641.41
TRI-9602	Codec Upgrade BO	\$4,859.19	\$641.41
TRI-9603	PTZ Camera L	\$4,049.19	\$534.49
TRI-9604	PTZ Camera M	\$4,049.19	\$534.49
TRI-9605	Ceiling Microphone A	\$967.95	\$127.77
TRI-9606	Microphone C	\$404.19	\$53.35
TRI-9607	Codec Upgrade BP	\$2,429.19	\$320.65
TRI-9608	Codec Upgrade BM	\$2,510.19	\$331.35
TRI-9609	Codec Upgrade BL	\$1,215.00	\$160.38
TRI-9610	Codec Upgrade BS	\$1,619.19	\$213.73
TRI-9611	Codec Upgrade BT	\$2,429.19	\$320.65
TRI-9612	Codec Network Module G	\$1,214.19	\$160.27
TRI-9613	Codec Network Module H	\$2,429.19	\$320.65
TRI-9614	Codec Network Module I	\$2,429.19	\$320.65
TRI-9615	Codec Network Module J	\$1,214.19	\$160.27
TRI-9616	PTZ Camera Wall Mount	\$40.50	\$5.35
TRI-9617	Codec Remote Control	\$166.86	\$22.03
TRI-9618	Wall Display	\$11,544.50	\$1,523.87
TRI-9619	8 Zone Time Clock	\$2,970.00	\$392.04

Part Number	Description	GSA Price	Maintenace Price
TRI-9620	Dual Power Sensor	\$330.00	\$43.56
TRI-9621	System Control Module	\$4,213.00	\$556.12
TRI-9622	Control Com Card	\$550.00	\$72.60
TRI-9623	Volume Controller Card	\$770.00	\$101.64
TRI-9624	Control Hub Card	\$2,772.00	\$365.90
TRI-9625	Card Frame	\$1,430.00	\$188.76
TRI-9626	Mini Card Frame	\$1,089.00	\$143.75
TRI-9627	System Control Power Supply A	\$132.00	\$17.42
TRI-9628	System Control Power Supply B	\$165.00	\$21.78
TRI-9629	Relay Card	\$550.00	\$72.60
TRI-9630	Audio Amplifier A	\$654.50	\$86.39
TRI-9631	Ceiling Microphone B	\$312.40	\$41.24
TRI-9632	KVM Switcher	\$819.50	\$108.17
TRI-9633	LCD Wall Mount C	\$218.90	\$28.89
TRI-9634	Custom Credenza A	\$5,500.00	\$726.00
TRI-9635	Custom Credenza B	\$8,250.00	\$1,089.00
TRI-9636	Electronic Screen A	\$2,717.00	\$358.64
TRI-9637	Screen Controller	\$225.94	\$29.82
TRI-9638	Component Interface A	\$979.00	\$129.23
TRI-9639	Tuner	\$759.00	\$100.19
TRI-9640	Switcher A	\$9,009.00	\$1,189.19
TRI-9641	Switcher B	\$45,529.00	\$6,009.83
TRI-9642	Scaler A	\$2,849.00	\$376.07
TRI-9643	Graphic Still Store	\$1,259.50	\$166.25
TRI-9644	Tilt-Up Panel	\$1,419.00	\$187.31
TRI-9645	Switcher C	\$3,729.00	\$492.23
TRI-9646	Switcher D	\$11,544.50	\$1,523.87
TRI-9647	Component Interface B	\$1,254.00	\$165.53
TRI-9648	Adapter Plate	\$220.00	\$29.04
TRI-9649	Ceiling Document Camera	\$2,528.90	\$333.81
TRI-9650	Speaker Set D	\$383.90	\$50.67
TRI-9651	LED Digital Display (3 color)	\$275.00	\$36.30
TRI-9652	Equipment Rack D	\$421.85	\$55.68
TRI-9653	Rack Power Supply A	\$85.80	\$11.33
TRI-9654	Rack Power Supply B	\$187.00	\$24.68
TRI-9655	Touch Panel D	\$8,800.00	\$1,161.60
TRI-9656	LCD Monitor D*	\$5,058.90	\$667.77

Part Number	Description	GSA Price	Maintenance Price
TRI-9657	LCD Monitor E*	\$16,489.00	\$2,176.55
TRI-9658	Projector D	\$8,250.00	\$1,089.00
TRI-9659	Audio System C	\$4,636.50	\$612.02
TRI-9660	LCD Monitor F*	\$32,890.00	\$4,341.48
TRI-9661	Rack Fan Panel	\$539.00	\$71.15
TRI-9662	Dual Monitor Single Network Room System*	\$70,521.95	\$9,308.90
TRI-9663	Dual Monitor Dual Network Room System*	\$115,542.00	\$15,251.54
TRI-9664	Dual Monitor Triple Network Room System*	\$158,815.00	\$20,963.58
TRI-9665	Trinity's Secure Multi-Media Communications System with Dual Network*	\$91,543.00	\$12,083.68
TRI-9667	Trinity's Secure Multi-Media Communications System with Triple Network Capability*	\$132,916.00	\$17,544.91
TRI-A118	Plasma Flat Panel High Resolution Upgrade	\$6,219.24	\$820.94
TRI-A1181	1 Total Turnkey 42" Dual Plasma Classic Series VTC system includes codec, visual concert, camera, peripheral equipment and secure management software	\$60,904.99	\$8,039.46
TRI-A1182	2 50" Plasma VTC and audio upgrade from an old FBI Legacy System includes AMX software and hardware integration using codec	\$88,102.75	\$11,629.56
TRI-B0001	1 Custom Room E	\$583,858.86	\$77,069.37
TRI-B0002	2 Custom Room F	\$1,404,693.46	\$185,419.54
TRI-B0003	3 Custom Room A	\$280,081.26	\$36,970.73
TRI-B0004	4 Custom Room B	\$329,179.79	\$43,451.73
TRI-B0005	5 Custom Room C	\$316,655.35	\$41,798.51
TRI-B0006	6 Custom Room D	\$359,486.89	\$47,452.27
TRI-9708	Codec System CO	\$4,859.19	\$641.41
TRI-9746	Codec System CP	\$4,049.19	\$534.49
TRI-9745	Codec System CQ	\$8,099.19	\$1,069.09
TRI-9747	Codec System CR	\$10,529.19	\$1,389.85
TRI-9753	Codec System CS	\$12,959.19	\$1,710.61
TRI-9754	Codec System CT	\$15,389.19	\$2,031.37
TRI-9741	Trinity's Custom Multi-Media Communications System Dual 52" System with HDX9002XLP	\$44,419.72	\$5,290.00
TRI-9720	Trinity's Custom Multi-Media Communications System Single 40" System with HDX9002XLP	\$34,908.79	\$4,573.00

Part Number	Description	GSA Price	Maintenance Price
TRI-9719	Trinity's Custom Multi-Media Communications System Single 40" System with HDX8004XLP	\$32,948.73	\$4,317.00
TRI-9716	Trinity's Custom Multi-Media Communications System Single 40" System with HDX7002XLP	\$20,709.51	\$2,713.00
TRI-9721	Trinity's Custom Multi-Media Communications System Single 52" System with HDX7002XLP	\$22,553.23	\$2,955.00
TRI-9738	Trinity's Custom Multi-Media Communications System Dual 40" System with HDX9002XLP	\$40,586.87	\$5,317.00
TRI-9735	Trinity's Custom Multi-Media Communications System Single 52" System with HDX9002XLP	\$40,299.73	\$5,280.00
TRI-9737	Trinity's Custom Multi-Media Communications System Dual 40" System with HDX8004XLP	\$36,029.63	\$4,720.00
TRI-9739	Trinity's Custom Multi-Media Communications System Dual 52" System with HDX7002XLP	\$26,673.16	\$3,494.00
TRI-9740	Trinity's Custom Multi-Media Communications System Dual 52" System with HDX8004XLP	\$38,750.76	\$5,077.00
TRI-9734	Trinity's Custom Multi-Media Communications System Dual 52" System with HDX8004XLP	\$34,630.02	\$4,537.00
TRI-9736	Trinity's Custom Multi-Media Communications System Dual 40" System with HDX7002XLP	\$23,790.82	\$3,117.00
TRI-8010	Installation - credenza	\$2,518.79	N/A
TRI-8020	Installation - T-Stand	\$3,022.55	N/A
TRI-8040	Installation - MCU A	\$5,037.58	N/A
TRI-8050	Installation - ISDN	\$2,015.03	N/A
TRI-8070	Custom Installations A	\$3,022.55	N/A
TRI-8080	Site Survey (per room) includes survey and room design	\$2,518.79	N/A
TRI-8101	De-installation of a visionwall	\$4,030.07	N/A
TRI-8102	Codec Installation	\$2,518.79	N/A
TRI-8103	Installation - Dual PlasmaPanel	\$2,518.79	N/A
TRI-8104	Installation - Single PlasmaPanel	\$1,511.27	N/A
TRI-8107	Settop Installation	\$901.73	N/A
TRI-8108	Desktop Installation	\$755.64	N/A
TRI-8109	Rollabout System Installation	\$1,511.27	N/A
TRI-8110	Custom Installations B	\$5,037.58	N/A
TRI-8119	Trinity System Deinstallation	\$2,518.79	N/A
TRI-9681	Phone Audio System A	\$1,722.01	\$205.00
TRI-9682	Phone Audio System B	\$1,243.44	\$148.00

Part Number	Description	GSA Price	Maintenance Price
TRI-9683	Phone Audio System C	\$2,391.17	\$285.00
TRI-9684	Phone Audio System D	\$1,434.87	\$171.00
TRI-9685	Phone Audio System E	\$2,726.17	\$325.00
TRI-9686	Phone Audio System F	\$3,252.60	\$387.00
TRI-9688	Sound Conditioner A	\$3,182.07	\$379.00
TRI-9689	Sound Conditioner B	\$3,182.07	\$379.00
TRI-9690	Sound Conditioner C	\$3,924.28	\$467.00
TRI-9691	Sound Conditioner D	\$3,426.40	\$408.00
TRI-9692	Sound Conditioner E	\$3,947.79	\$470.00
TRI-9693	Mixer A	\$2,211.50	\$263.00
TRI-9694	Mixer B	\$2,952.02	\$352.00
TRI-9677	Codec System BG	\$9,570.57	\$1,140.00
TRI-9678	Codec System BH	\$7,656.29	\$912.00
TRI-9679	Codec System CU	\$8,099.19	\$971.90
TRI-9680	Codec System CV	\$6,479.19	\$777.50
TRI-9702	Soundmasking Source A	\$5,934.27	\$707.00
TRI-9703	Soundmasking Source B	\$6,699.98	\$798.00
TRI-9704	Soundmasking Source C	\$6,939.27	\$827.00
TRI-9705	Portable Eavesdropping	\$5,742.84	\$684.00
TRI-9706	Codec System BK	\$2,870.58	\$342.00
TRI-9707	Codec System BL	\$3,349.15	\$399.00
TRI-9709	Codec System BN	\$10,609.15	\$1,264.00
TRI-9710	Codec System BO	\$11,425.24	\$1,361.00
TRI-9711	Codec System BP	\$13,057.41	\$1,555.00
TRI-9712	Codec System BQ	\$15,097.63	\$1,798.00
TRI-9713	Codec Upgrade BG	\$1,631.34	\$194.00
TRI-9715	Codec Upgrade BH	\$2,658.16	\$317.00
TRI-9714	Codec System BR	\$17,719.69	\$2,110.00
TRI-9722	Codec System BS	\$8,297.74	\$988.00
TRI-9723	Codec System BT	\$5,463.26	\$651.00
TRI-9724	Codec Upgrade BI	\$4,388.57	\$523.00
TRI-9725	Codec Upgrade BJ	\$732.97	\$87.00
TRI-9726	Codec System BU	\$10,247.28	\$1,220.00
TRI-9727	Codec System BV	\$12,196.83	\$1,453.00
TRI-9728	Codec System BW	\$9,772.07	\$1,164.00
TRI-9729	Codec System BX	\$8,400.17	\$1,000.00
TRI-9730	Codec System Upgrade BK	\$972.25	\$116.00

Part Number	Description	GSA Price	Maintenance Price
TRI-9731	Codec System BY	\$17,587.04	\$2,095.00
TRI-9732	Codec System BZ	\$18,564.33	\$2,211.00
TRI-9733	Codec System CA	\$17,587.04	\$2,095.00
TRI-9695	Power Amplifier A	\$1,742.16	\$207.00
TRI-9696	Power Amplifier B	\$1,981.45	\$236.00
TRI-9697	Power Amplifier C	\$2,369.34	\$282.00
TRI-9698	Generator	\$2,273.63	\$271.00
TRI-9699	Level Control	\$2,369.34	\$282.00
TRI-9700	Sound Conditioner F	\$1,148.57	\$137.00
TRI-9687	VSX Carrying Case	\$837.92	\$100.00
TRI-9701	Sound Conditioner G	\$1,818.57	\$217.00
TRI-9144	Headset	\$448.34	\$53.80
TRI-9717	Trinity's UnSecure Touchscreen access Control Software Intrerface including hardware, and GUI for HDX7002XLP	\$6,924.16	\$825.00
TRI-9146	Visual Concert	\$1,510.27	\$181.23
TRI-9147	Text Burster for Security Messages	\$761.68	\$91.40
TRI-9148	Two Way Touch Screen & Interface Module	\$7,254.12	\$870.49
TRI-9163	VCR/DVD Combo Unit	\$235.76	\$28.29
TRI-9173	VCR B	\$99.74	\$11.97
TRI-9174	DVD Player B	\$397.97	\$47.76
TRI-9179	Custom Installations C	\$3,022.55	N/A
TRI-9202	BRI Module	\$1,258.56	\$151.03
TRI-9404	Installation - MCU B	\$4,332.32	N/A
TRI-9674	On-site Installation, Integration and Technical Support Services - SATCOM Engineer Level (daily rate)	\$1,265.27	N/A
TRI-9676	On-site Satellite Installation, Integration and Technical Support Services (daily rate)	\$1,103.23	N/A
TRI-9718	Installation & Training for Trinity's Custom Multimedia System	\$3,526.31	N/A
TRI-9441	Installation & Testing Secure Management System	\$2,015.03	N/A
TRI-A1180	Plasma Flat Panel High Resolution Upgrade	\$6,219.24	\$1,243.85
TRI-9593	Installation and Testing for Secure Multi-Media Communications Systems	\$5,894.21	N/A

Part Number	Description	GSA Price	Maintenace Price
TRI-9666	Installation and Testing for Secure Multi-Meda Communications System with Dual Network Capability	\$9,000.00	\$1,188.00
TRI-9668	Installation and Testing for Secure Multi-Meda Communications System with Triple Network Capability	\$10,900.00	\$1,438.80
TRI-9669	Tech Support Billing Rate per hour - technician audio visual installation and training	\$75.00	N/A
TRI-9670	Tech Support Billing Rate per hour - senior technician SVTC/audio visual/IAF/satellite diversity installation, training, and documentation	\$85.00	N/A
TRI-9671	Tech Support Billing Rate per hour – engineer tech, basic audio visual design, drawings, documentation, installation and training	\$95.00	N/A
TRI-9672	Tech Support Billing Rate per hour – engineer (1 - junior) audio visual design, engineering, configuration, programming, documentation, installation and training	\$105.00	N/A
TRI-9673	Tech Support Billing Rate per hour - inventory specialist inventory and property management support	\$49.50	N/A
TRI-8112	Tech Support Billing Rate per Hour Consulting/Design Engineer for A/V or Network Communications	\$251.88	N/A
TRI-9755	Trinity Mini Smart Mobile Case includes H/W & Devices	\$4,495.00 (units 1-4) \$4,444.67 (units 5-24) \$4,394.35 (units 25-49) \$4,344.02 (units 50+)	
TRI-9755M	Annual Maint on Trinity Mini Smart Mobile Case	\$3,000.00 (units 1-4) \$2,966.75 (units 5-24) \$2,933.50 (units 25-49) \$2,900.25 (units 50+)	

Part Number	Description	GSA Price	Maintenance Price
TRI-9755M-3	3 Year Maint on Trinity Mini Smart Mobile Case	\$7,200.00 (units 1-4) \$7,119.40 (units 5-24) \$7,038.79 (units 25-49) \$6,958.19 (units 50+)	