

**Department of Veterans Affairs**  
**Federal Supply Schedule**  
**Authorized Federal Supply Schedule Price List**

On-line access to contract ordering information, terms and conditions, up-to-date pricing, and the option to create an electronic delivery order, are available through *GSA Advantage!* a menu-driven database system. The INTERNET address for *GSA Advantage!* is: [GSA Advantage.gov](http://GSAAdvantage.gov)

**DENTAL HANDPIECE REPAIR SERVICES**

**FSC Group 65, Part II Section C**  
**FSC Class 6520**

Contract No: V797P-3122M

Contract Period: November 15, 2006 - November 14, 2011

For more information on ordering from Federal Supply Schedules  
Click on the FSS Schedules button at [fss.gsa.gov](http://fss.gsa.gov)



**RPM Medical Technologies**  
**223 West Anderson Lane, Suite B/202**  
**Austin, Texas 78752**  
**Phone: 1-(800)-858-3089**  
**Fax: (512)-219-6373**  
[emackey@myrpmmedical.com](mailto:emackey@myrpmmedical.com)  
[www.GSAAdvantage.Gov](http://www.GSAAdvantage.Gov)

Size of Business: **Service Disabled Veteran-Owned Small Business (SDVOSB)**  
TIN: **06-1761885**

## Customer Information

1. Table of awarded special item numbers with appropriate cross-reference to page numbers. C-100 page 3-4
2. Maximum Order: 500,000.00 (C-100)
3. Minimum Order: No minimum order required
4. Geographic Coverage (delivery area): 50 States, D.C. and Puerto Rico
5. Points of Production: 223 West Anderson Lane, Suite B202, Austin, TX 78752
6. Prices shown herein are net, discount already deducted.
7. Quantity Discount: 10-19 units, additional 2%, 20+ units, additional 3% discount taken off invoice for facilities that establish BPA's against this schedule.
8. Prompt payment terms: Net 30 days.
- 9a. Government commercial credit card accepted with no additional discount granted.
- 9b. Government commercial credit card is accepted above the micro-purchase level, with no additional discount granted.
10. Foreign items: None
- 11a. Time of delivery: High speed drill rebuilds, within 7 days after approval of repair order (ARO). Low speed motor overhauls, within 7-12 days after approval of repair order.
- 11b. Expedited Delivery: Within 72 hours ARO for high speed turbine replacement, subject to availability of parts. Government pays the difference between normal and expedited carrier charges.
12. F.O.B. Point: Destination to 48 contiguous states, and F.O.B points of exportation for Alaska, Hawaii and Puerto Rico.
13. Ordering Address: RPM Medical Technologies, 223 West Anderson Lane, Suite B202, Austin, TX 78752
- 13b. Ordering Procedures: Ordering procedure information for supplies and services can be found at GSA/FSS Schedule homepage [www.fss.gsa.gov/schedules](http://www.fss.gsa.gov/schedules) as well as for Blanket Purchase Agreement (BPA) information. Orders may also be placed by telephone Toll-Free at (800) 858-3089, Fax (512) 219-6373 or email at [emackey@myrpmmedical.com](mailto:emackey@myrpmmedical.com)

14. Payment Address: RPM Medical Technologies, 223 West Anderson Lane, Suite B202, Austin, TX 78752

15. Warranty Provisions: The contractor warrants and implies that the items of repair delivered hereunder are merchantable, fit for use for the particular purpose and will be free from defects in material and workmanship for a period of not less than 120 days from date of acceptance, unless otherwise noted. Exceptions to the 120 day warranty period apply as follows: Turbine replacements 180 days warranty. RPM Medical Technologies will replace at its option all parts found defective within the periods noted.

16. Return Goods Policy: If a shipping error occurs due to Contractor, RPM Medical will pay shipping charges both ways for return/exchange of goods. For customer errors involving ordering facilities, the customer pays return shipping charges. No restocking fee will apply in either case. Contractor will accept customers return orders up to 30 days. Please call RPM Medical Technologies' Customer Service Department (between 0900-1700 hours CST for a "Return Authorization (RA#)" number at (800) 858-3089 or by fax at (512) 219-6373 before returning any goods to RPM Medical Technologies. Unauthorized returns will not be accepted and will be returned at the customer's expense.

17. Export Packaging Changes: NA

18. Terms and conditions of rental, maintenance and repair: See item #15

19. Terms and conditions of repair parts. See item #15

20. List of authorized participating dealers: None

21. Preventative Maintenance: The lack of preventative maintenance protocol on the part of the user could be considered negligence and may void their warranty with the Contractor.

22. Special attributes such as environmental: None

23. DUNS #: 02-246-1052

24. Cage Code: 1BYD8

25. Government Registrations updated in CCR and ORCA online databases.

26. SBA and VA certifications: Hub Zone and Verified Service Disabled Veteran-Owned Small Business (SDVOSB)

**RPM Medical Technologies**  
**Authorized Federal Supply Schedule**

**PRICE LIST**

**Handpiece Repair Services**

<b>SIN</b>	<b>Repair #</b>	<b>Repair Service Description</b>	<b>FSS Net Price</b>
C-100	HSR11	Impact Air 45 Turbine Rebuild	\$105.75
C-100	HST21	Impact Air 45 Type Turbine Repl	\$171.00
C-100	HSR12	Star 430SWL, 430 SW, Solara Rebuild	\$105.75
C-100	LSO 32	Star Titan 3, 5000 rpm, 20,000 rpm, Motor Overhaul	\$217.58
C-100	LSO 35	Star Nose Cone, Torque Multiplier, MTA	\$202.50
C-100	LSO 36	Star Ball Bearing Angles, Overhaul	\$179.10
C-100	HST22	Star 430 SWL, SW, SolaraType Turbine Replacement	\$171.00
C-100	HSR13	Kavo Bella Torque Lux 2, 640B, 642B, 643B Turbine Replacement	\$179.10
C-100	HSR 25	Kavo Mira Lux 3, 635B, Turbine Replacement	\$179.10
C-100	HSR 26	Kavo Gentle Torque, 6000B, 6500B, Turbine Replacement	\$179.10
C-100	HSR 27	Kavo Opti-Torque Lux 3, 647B, 649B, Turbine Replacement	\$179.10
C-100	HSR 28	Kavo Supertorque, Powertorque, 659B,646B, Turbine Replacement	\$179.10
C-100	HRS 23	Kavo Bella Torque Lux 2, 640B, 642B, 643B Turbine Rebuild	\$105.75
C-100	HRS 29	Kavo Mira Lux 3, 635B, Turbine Rebuild	\$105.75
C-100	HRS 30	Kavo Gentle Torque, 6000B, 6500B, Turbine Rebuild	\$105.75
C-100	HRS 31	Kavo Opti-Torque Lux 3, 647B, 649B, Turbine Rebuild	\$105.75
C-100	HRS 32	Kavo Supertorque, Powertorque, 659B, 646B, Turbine Rebuild	\$105.75
C-100	LSO23	Kavo 10K Attachment Overhaul	\$202.50
C-100	LSO24	Kavo Intraflex Lux 2307, Overhaul Lv 1	\$382.50
C-100	LSO25	Kavo Intraflex Lux 2307, Overhaul Lv 2	\$477.90
C-100	LSO 99	Kavo 2325 LN Contra Angle w/ Fixed Head Motor Overhaul	\$477.90
C-100	LSO 100	Kavo 2320 LN Contra Angle Motor w/o Head Overhaul	\$477.90
C-100	LSO26	Kavo 67 LDN, 68 LH, LDN, 62 GN, 80 LD Head Overhaul	\$179.10
C-100	LSO 37	Kavo Low Speed -Replace Body Housing	\$292.50
C-100	LSO 31	Kavo 181 K INTRAair Motor Overhaul	\$420.30
C-100	LSO27	Clean & remove dents and debri from heads	\$94.50
C-100	LSO 28	Kavo Type Replace PB Back Cap	\$94.50
C-100	HSR 20	Midwest Stylus, Tradition, Quiet Air Turbine Rebuild	\$105.75
C-100	HSR 17	Midwest Stylus, Tradition, Quiet Air Turbine Replacement	\$171.00
C-100	LSO 29	Midwest Shorty Overhaul	\$217.58
C-100	LSO 33	Midwest RDH Hygiene Overhaul	\$217.58
C-100	LSO 30	Midwest Type LS Replace Body Housing	\$103.50
C-100	HSR 22	Limited High Speed Repair	\$71.10
C-100	HSR 19	Kavo Type Replacement HS/PB Cap	\$94.50
C-100	LSO34	Limited Low Speed Repair	\$89.10
C-100	HSR 14	W&H Adec Synea, Toplight,Trend, Turbine Rebuild	\$105.75
C-100	HSR 24	W&H Adec Synea, Toplight,Trend, Turbine Replacement	\$179.10
C-100	HSR 15	W&H Adec Attachment Overhaul	\$202.50
C-100	LSO 32	W&H Adec WA-56 LT, WS-75 E/KM, LT 25 Overhaul	\$420.30

C-100	LSO 38	W&H LS AP-44 Motor Overhaul	\$202.50
C-100	HSR 16	Sabra OMS-45 Turbine Rebuild	\$105.75
C-100	HSR 21	Sabra OMS-45 Turbine Replacement	\$179.10
C-100	HSR 17	Clean or clear air & water lines	\$45.00
C-100	HSR 18	Remove locked burs	\$30.38
C-100	OSR 1	Hall Surgairtome II Oral Surgery Handpiece Overhaul	\$315.00
C-100	OSR 2	Hall Bur Guard	\$112.50
C-100	OSR 3	Hall Surgical Air Hose	\$157.50
C-100	OSR 4	Stryker 296,2296, Command & Command 2	\$405.00
C-100	OSR 5	Stryker 2296-300 Impaction Drill Overhaul	\$405.00
C-100	HSR 00	Complimentary Clean Swivel Adapter-All Handpiece Models	N/A
C-100	HSR 01	Complimentary Clean Fiber-Optics	N/A
C-100	HSR 03	Complimentary Extended Handpiece Cleaning	N/A
C-100	HSR 04	EQUIPMENT RETURNED: Beyond Economical Repair Condition	N/A
C-100	HSR 05	Complimentary Repair Estimate	N/A
C-100	HSR 06	Complimentary Customer Warranty Tracking	N/A




# Concentricity Testing with Every Repair

**Avoid Premature Turbine Replacement!**



**High-Speed Handpiece**



**Concentricity Gauge**

RPM Medical Technologies measures spindle concentricity to International Standards Organization (ISO) standards. Our technicians are thoroughly trained by Original Equipment Manufacturers (OEM) in all areas of handpiece repair. One important component of our repair is concentricity testing on the handpiece turbine. With the turbine rotating at speeds up to 500,000 rpm, even a slight deviation from true center can drastically reduce the lifespan of the turbine. *Concentricity, even more than the quality of bearings, is the single most important aspect of a quality repair.* Our technicians use proprietary test equipment, called a concentricity gauge, to perform concentricity tests to insure every high-speed repair meets manufacturer specifications. ISO has set the benchmark for dental turbines at .0011 inches or less of total indicator run-out (TIR). These tolerances are maintained on all of our high-speed repairs. This service alone can save you substantial equipment repair costs.