

TERMS:

1. TABLE OF AWARDED SPECIAL ITEM NUMBERS WITH APPROPRIATE CROSS-REFERENCE TO PAGE NUMBERS
SINS PAGE
A-9 15-16
A-41 16
A-200 2-15
 2. MAXIMUM ORDER: NO LIMIT
 3. MINIMUM ORDER: NONE
 4. GEOGRAPHIC COVERAGE (DELIVERY AREA): 50 STATES, D.C. AND PUERTO RICO
 5. POINTS OF PRODUCTION: FIFE, WA
 6. PRICES SHOWN HEREIN ARE NET, DISCOUNT DEDUCTED.
 7. QUANTITY DISCOUNTS:
A-200 (ALL): ADDITIONAL 2% OFF INVOICE FOR REPAIR ORDERS IN EXCESS OF \$5,000.
A-9: 5-14 UNITS = 22% OFF LIST PRICE; 15+ UNITS = 36-38% OFF LIST PRICE.
A-41: NO DISCOUNT
 8. PROMPT PAYMENT TERMS: 2% 15 DAYS, NET 30 DAYS. ALSO APPLIES TO GOVERNMENT CREDIT CARD ORDERS
 - 9a. GOVERNMENT COMMERCIAL CREDIT CARD ACCEPTED. PROMPT PAYMENT DISCOUNT APPLIES 2%, 15 DAYS
 - 9b. GOVERNMENT COMMERCIAL CREDIT CARDS ARE ACCEPTED ABOVE THE MICRO-PURCHASE THRESHOLD.
 10. FOREIGN ITEMS: NONE
 - 11a. TIME OF DELIVERY: WITHIN 2-7 BUSINESS DAYS, ARO OR AFTER AUTHORIZED FOR REPAIR
SEE PAGE 17 FOR DETAILS OF REPAIR TURN-AROUND TIMES.
 - 11b. EXPEDITED DELIVERY: 1-3 BUSINESS DAYS ARO, OR AFTER AUTHORIZED FOR REPAIR.
- NO ADDITIONAL CHARGE TO THE GOVERNMENT
12. F.O.B. POINT: DESTINATION TO 48 CONTIGUOUS STATES, F.O.B. POINT OF EXPORTATION FOR ALASKA, HAWAII, AND PUERTO RICO.
 - 13a. ORDERING ADDRESS: BPI MEDICAL, INC.
4813 PACIFIC HWY E
FIFE, WA 98424
 - 13b. ORDERING PROCEDURES: FOR ALL PRODUCTS, CALL 800-550-2367 TO ORDER
 14. PAYMENT ADDRESS: BPI MEDICAL, INC.
4813 PACIFIC HWY E
FIFE, WA 98424
 15. WARRANTY PROVISION: ONE YEAR ON RIGID SCOPE REPAIR
6 MONTHS ON INSTRUMENTS, FLEXIBLE SCOPES, HANDPIECES AND ALL OTHER REPAIR SERVICES.
WARRANTY COVERS MATERIALS AND WORKMANSHIP.
WARRANTY DOES NOT COVER DAMAGE CAUSED BY MISUSE OR MISHANDLING.
 16. RETURN GOODS POLICY: FOR SINS A-9 AND A-41:
MERCHANDISE RETURNED WITHOUT OUR PERMISSION WILL NOT BE ACCEPTED FOR CREDIT.
WITH RETURNED ITEMS, DATE OF PURCHASE AND BPI MEDICAL INVOICE NUMBER MUST BE SHOWN ON PACKING LIST.
NO CREDIT ALLOWED ON RETURN OF SPECIAL OR ALTERED ITEMS.
STERILE PACKAGED ITEMS MAY BE RETURNED FOR CREDIT ONLY IF RETURNED IN THE ORIGINAL UNOPENED PACKAGE.
NO PRODUCT MAY BE RETURNED FOR CREDIT AFTER 90 DAYS FROM INVOICE DATE.

IF A SHIPPING ERROR OCCURS DUE TO BPI MEDICAL'S ERROR, BPI MEDICAL WILL PAY FREIGHT BOTH WAYS FOR RETURN/EXCHANGE OF GOODS.

IF AN ORDERING FACILITY ERROR OCCURS, THE ORDERING FACILITY WILL PAY RETURN FREIGHT.

NO HANDLING CHARGE WILL APPLY.

PLEASE CALL THE CUSTOMER SERVICE DEPARTMENT FOR A RETURN AUTHORIZATION NUMBER, AT 800-550-2367.

17. DATA UNIVERSAL NUMBER SYSTEM (DUNS) NUMBER: 18-003-4337

18. NOTIFICATION REGARDING REGISTRATION IN CENTRAL CONTRACTOR REGISTRATION (CCR)

DATABASE REGISTERED THROUGH XXX 25, 2003

Price Lists

FLEX

BPI Medical Flexible Scope Service

Code	Repair Description	Price
535001	Ang adjustment (minor ang)	\$123.58
535002	Ang full (major ang)	\$204.18
535003	Ang Rebuild	\$1,611.91
535004	Ang control body clean	\$285.85
535005	Ang cntrl knob shaft replace	\$444.36
535006	005 Add Replace Control Knob	\$84.33
535007	005 Add Replace Control Knob	\$257.91
535009	Angulation wire repair - minor	\$193.43
535010	Ang wire/coil repl.lrg channel	\$1,069.23
535011	Ang wire/coil repl.sm.channel	\$2,050.00
535012	Angulation system cleaning	\$838.19
535013	Angulation stopper attach	\$170.86
535014	Aux water cap replacement	\$91.99
535015	Aux wtr port leak, valve repl	\$84.82
535016	Aux water port housing repl.	\$311.64
535017	A/W channel repl. & sheath	\$577.06
535018	A/W channel reattach/repair	\$209.55
535019	Air/Water seperator seals	\$61.25
535020	A/W channel/Aux chnl clear	\$92.42
535021	A/W Connector Realign	\$61.25
535050	Bendng sect. repair BF-LF	\$85.97
535051	Bend. sect. repair CF-GIF-TJF	\$204.18
535052	Biohazard cleaning	\$277.03
535053	Biopsy channel repl. /w sheath	\$706.02
535054	Biopsy ch. Repl. Dbl. w/sheath or AL scope	\$1,069.23
535055	Bpsy ch. Reatt/resize blocked	\$163.34
535056	Biopsy port-fiberscope repr.	\$285.85
535057	Boot replacement ins. Tube	\$279.40
535058	Boot replacement L/G tube	\$1,235.80
535059	Boot reattach	\$102.09
535060	Button realignment	No charge
535061	Biopsy Ch. Repl Bronch/Fiberscope	\$1,144.46
535090	C-cover replacement w/sheath	\$319.16
535091	CO2 port repair + pin replacement	\$204.18
535092	CCD chip repair (Quote)	Quote
535093	CCD chip/obj assembly (clean)	\$368.24
535094	CCD chip rewire	\$1,600.00
535095	Coil pipe attach at distal w/sheath & B/C	\$1,069.23
535100	Drum cable repair (one set=two cables)	\$538.38
535109	E/C Reround	\$91.34
535110	E/C cnctr. align.pin install	\$151.52
535111	E/C connector rewire	\$873.30
535112	E/C cnctr repl. + E/C rewire	\$1,589.70
535113	E/C connector clean	\$81.67
535114	Elevator adjustment	\$138.62
535115	Elevator ctrl cable repl+shth.	\$375.79
535116	Elevator channel repl+sheath	\$531.93
535117	Elvtr. tube in cntr body/s-cover	\$369.31
535118	Elevator stopper replacement	\$151.52
535119	ETO pin replacement	\$130.05
535120	Eyepiece lens assmb. cleaning	\$254.68
535121	Eyepiece replacement	\$450.00

BPI Medical Flexible Scope Service

Code	Repair Description	Price
535150	Fluid invasion (minor)	No charge
535151	Fluid invasion (major)	\$321.31
535155	Forcep port reseal	\$102.09
535156	F/E knob replacement (100 series)	\$111.22
535163	Adjust tension knob AL	\$193.43
535164	Insertion tube replace AL/Pentax	\$3,277.55
535165	Ins. tube support boot extndr.	\$157.58
535166	Insertion tube repair/reseal	\$106.39
535167	Insertion tube realign	\$367.52
535168	Ins. tube replacement-large	\$2,686.52
535169	Ins. tube repl. Img. bundle F/O	\$4,500.00
535170	Insertion tube realign, Bronch	\$122.51
535171	Rebuild or replace Tension Control	\$929.24
535190	L/G conn. - pins, repair leak	\$119.28
535191	L/G base seal	\$42.98
535192	L/G bundle repl. w/sheath	\$1,213.23
535193	L/G connector ring - adjust	\$49.00
535194	L/G tube reround and/or insert	\$59.10
535195	L/G tube replacement video	\$1,289.53
535196	L/G tube repl. fiberscope	\$641.54
535197	L/G lens repair/replace (each)	\$149.22
535198	L/G or objective lens reseal	\$68.36
535199	L/G housing repl. 140/160 ser.	\$617.90
535200	L/G base & rod ends tightened	No charge
535201	L/G rod end, clean debris	\$61.25
535202	L/G Tube Repair/Reseal	\$122.51
535204	L/G bundle clean distal	\$451.34
535205	L/G bundle repl. TJF/JF/BF	\$1,735.49
535225	Mesh repair (minor) reattach	\$122.51
535226	Mesh repl./sheath inc bio channel	\$733.87
535227	Mask reattach	\$248.23
535228	Mask clean	\$245.01
535235	Nozzle replacement 100 ser.	\$98.86
535236	Nozzle repl. 140,160 series	\$110.04
535245	O-ring replacement	\$50.81
535250	Polish lenses	\$61.25
535251	Reseal Control Body	\$81.67
535255	Seal-suction,A/W, ground port	\$68.03
535256	Sheath repl. (bending rubber)	\$130.78
535257	Suction channel replacement	\$228.89
535258	Suction Cylinder Replacement	\$506.14
535259	Switch replace (#4)	\$106.39
535260	Switch and btn #1 repl 100's	\$173.01
535261	Switch btn #1 repl 140/160	\$228.89
535262	Switch head replacement	\$440.59
535998	Misc. Minor Repair L1	\$60.93
535999	Misc. Minor Repair L2	\$138.46

BPI Medical Rigid Endoscope Service

Code		Repairs	Price
525001	LEVEL 1	Complete exterior cleaning, polishing of fiberoptics and window, optical adjustment, vacuum and seal, functional, hot/cold liquid and shock tests.	\$200.00
525002	LEVEL 2	Complete interior cleaning, polishing of fiberoptics and window, stainless steel tube realignment and kinks repair, ocular window replacement, optical adjustment, vacuum and seal, functional, hot/cold liquid and shock tests.	\$300.00
525003	LEVEL 3	Complete interior cleaning, bonding and polishing of the light fiber, repair or replace optical window, stainless steel tube realignment and kinks repair, replacement of two rod or achromatic lenses, optical adjustments, vacuum and seal, functional, hot/cold liquid and shock tests.	\$499.99
525004	LEVEL 4	Complete interior cleaning, bonding and polishing of the light fiber, repair or replace optical window, stainless steel tube realignment and kinks repair, replacement of the objective lens system, replacement of two rod or achromatic lenses, optical adjustment, vacuum and seal, functional, hot/cold liquid and shock tests.	\$555.99
525005	LEVEL 5 Video	Complete interior cleaning, bonding, polishing and repair of the light fiber, repair or replace optical window, stainless steel tube realignment and kinks repair, replacement of the objective lens system, replacement of up to two rod or achromatic lenses, optical adjustments, vacuum and seal, functional, hot/cold liquid and shock tests.	\$579.99
525006	LEVEL 6	Complete rebuild; replacement of light fiber and stainless steel tubing, complete interior cleaning, replacement of optical window and objective lens system, replacement of mechanical parts, replacement of up to two rod or achromatic lenses, optical adjustments, vacuum and seal, functional, hot/cold liquid and shock tests.	\$715.99
<u>OPERATING LAPAROSCOPES:</u>			
525007	LEVEL 7	Complete interior cleaning, polishing of fiberoptics and window, stainless steel tube realignment and kinks repair, ocular window replacement, optical adjustment, vacuum and seal, functional, hot/cold liquid and shock tests.	\$635.99
525008	LEVEL 8	Complete interior cleaning, bonding and polishing of the light fiber, repair or replace optical window, stainless steel tube realignment and kinks repair, replacement of two rod or achromatic lenses, optical adjustments, vacuum and seal, functional, hot/cold liquid and shock tests.	\$923.99
525009	LEVEL 9	Complete interior cleaning, bonding and polishing of the light fiber, repair or replace optical window, stainless steel tube realignment and kinks repair, replacement of the objective lens system, replacement of two rod or achromatic lenses, optical adjustment, vacuum and seal, functional, hot/cold liquid and shock tests.	\$1,091.99
525010	LEVEL 10	Complete rebuild; replacement of light fiber and stainless steel tubing, complete interior cleaning, replacement of optical window and objective lens system, replacement of mechanical parts, replacement of up to two rod or achromatic lenses, optical adjustments, vacuum and seal, functional, hot/cold liquid and shock tests.	\$1,259.99
** Specialty Scopes – Sinus, Semi Rigid, Etc...Quote			
<u>Semi Rigid Scopes</u>			
525011	LEVEL 11	Image Guide/ Objective	\$1,599.98
525012	LEVEL 12	Image Guide/ Objective, Tubing and Fibers	\$1,999.98
<u>Additional Parts:</u>			
525201		Rod lenses	\$56.00
525202		Window	\$52.00
525203		Eyepiece	\$76.00
525204		Light Cone - SEE PART NUMBER	\$150.00
525205		Solderable Window	\$100.80

BPI Medical Pneumatic Motor Service

Code	Repair Description	Price
LARGE BONE		
<i>Hall 5044-02 & 5067-02 Oscillating Saw, Hall 5044-01 & 5067-01 Drill Reamer, Hall 5059-05 Sternum Saw, 3M Sternum Saw, Saros Saw 6090, Hall 5044-03 & 5067-03 Recip. Saw, Hall 5053-13 & 5053-04 Wire Driver, Hall 5059-1 Neuro Driver, Crainotome 5067-04 Trauma, Crainotome 5059 Neurodriver, 3M N293 Neuro Drive Large Attachment, 3M L100 Maxi Driver, 3M K100 Mini Driver & K200 Mini Driver II, Micro Aire 6640 Smart Driver</i>		
444001 LEVEL 1	Complete diagnostic. Five point exterior inspection and documentation. Minor repair stuck burr or blade/chuck repair. Minor repair trigger and switch. Complete specifications test.	\$135.00
444002 LEVEL 2	Complete diagnostic. Five point exterior inspection and documentation. Ten point interior inspection and documentation. Clean and lubricate all internal parts. Replace all worn o-rings, clips and seals. Complete specifications test.	\$225.00
444003 LEVEL 3	Complete diagnostic. Five Point exterior inspection and documentation. Ten Point interior inspection and documentation. Clean and lubricate all internal parts. Replace all worn o-rings, clips and seals. Replace bearings and vanes. Complete specifications test.	\$387.01
SMALL BONE		
<i>3M A200 Minos H.S. drill, Hall Micro 100's, Surgairtome, Osc. Saw, Sag. Saw, Drills, Micro Aire Module 2000, Hall Ultra Power, Stryker Microtome, Stryker Rototome, Stryker Osc. Saw 277-30</i>		
444070 LEVEL 1	Complete diagnostic. Five point exterior inspection and documentation. Minor repair stuck burr or blade/chuck repair. Minor repair trigger and switch. Complete specifications test.	\$135.00
444071 LEVEL 2	Complete diagnostic. Five point exterior inspection and documentation. Ten point interior inspection and documentation. Clean and lubricate all internal parts. Replace all worn o-rings, clips and seals. Complete specifications test.	\$207.00
444072 LEVEL 3	Complete diagnostic. Five Point exterior inspection and documentation. Ten Point interior inspection and documentation. Clean and lubricate all internal parts. Replace all worn o-rings, clips and seals. Replace bearings and vanes. Complete specifications test.	\$387.01
Zimmer Hall Dermatome 8801		
444004 LEVEL 1	As above	\$180.00
444005 LEVEL 2	As above	\$270.00
444006 LEVEL 3	As above	\$450.01
444007	Calibration & Parts	\$309.65
Dental Handpiece		
444083 LEVEL 1	Stuck burr, plus the above	\$90.00
444084 LEVEL 2	Replace turbine, plus the above	\$180.00
HOSES		
<i>Hoses, Hall, 3M, MicroAire</i>		
444150 LEVEL 1	Complete Diagnostic. Straighten Connectors. Replace O-ring. Complete Specifications Test.	\$99.00
444151 LEVEL 2	Complete Diagnostic. New inner/outer hose. New clips, spring, and O-ring. Straighten Connectors. Complete Specifications test.	\$112.50
444152	N2 adaptor repair	\$36.00
444153	N2 adaptor replacement	\$54.00
444162	Schrader Replacement	\$144.00
444167	Hoses - Other	Quote

BPI Medical Pneumatic Motor Service

Code	Repair Description	Price
LG Synthes Hose		
444140 LEVEL 1	Complete Diagnostic. Straighten Connectors. Replace O-ring. Complete Specifications Test.	\$99.00
444141 LEVEL 2	Complete Diagnostic. New inner/outer hose. New clips, spring, and O-ring. Straighten Connectors. Complete Specifications test.	\$135.00
Integrated Motor Hoses		
Hall Ototome 5056-02, Anspatch Black Max, Midas Rex Motor		
444130 LEVEL 1	Complete diagnostic. Five point exterior inspection and documentation. Minor repair stuck burr or blade/chuck repair. Minor repair trigger and switch. Complete specifications test.	\$152.10
444131 LEVEL 2	Complete diagnostic. Five point exterior inspection and documentation. Ten point interior inspection and documentation. Clean and lubricate all internal parts. Replace all worn o-rings, clips and seals. Complete specifications test.	\$382.51
444132 LEVEL 3	Complete diagnostic. Five Point exterior inspection and documentation. Ten Point interior inspection and documentation. Clean and lubricate all internal parts. Replace all worn o-rings, clips and seals. Replace bearings and vanes. Complete specifications test.	\$445.51
444134	Midas Rex Inner Hose Repair	\$94.50
444135	Midas Rex Inner and Outer Hose Repair	\$202.50
444163	Sarns Saw Cable	\$157.50
ATTACHMENTS		
Micro Aire Wire Driver attachment, Hall Angle attachment, Micro Aire 2100, 3M K III, Synthes Wire Driver		
444190 Level 1	Complete diagnostic. Five point exterior inspection and documentation. Minor repair stuck burr or blade/chuck repair. Minor repair trigger and switch. Complete specifications test.	\$121.50
444191 Level 2	Complete diagnostic. Five Point exterior inspection and documentation. Ten Point interior inspection and documentation. Clean and lubricate all internal parts. Replace all worn o-rings, clips and seals. Replace bearings. Complete specifications test.	\$292.50
444180	Minor chuck work	\$44.55
444181	Major Chuck Work or Replace Chuck	Quote
BURR GUARDS		
444200	Replace up to two bearings, clean, lubricate and inspect. Test operation. Additional bearings	\$45.45 Quote
DRILLS, Cranial and Hand		
444210	Synthes Drill Adapter 511.750	\$113.40
444181	Chuck Replacement	\$207.00
MACHINE WORK		
444304	Machine Work	\$108.00

BPI Medical Instrument Service

Code	Repair Description	Price
401004	Arthroscopy Punch/Scissor/Grasper	\$17.10
401006	Aspirating Needle	\$17.10
401128	Curette, Bone/Adenoid/Cervical/Regular	\$10.00
401129	Bone Cutter	\$30.00
401131	Greenberg Arm Refurbish	\$45.37
401132	Greenberg Arm, New Cable	\$53.33
401133	Greenberg Arm, New Ball Joint	\$14.32
401134	Greenberg Arm, New Handle	\$41.91
401137	Burrs	\$8.00
401140	Greenberg Arm, New Side Clamp	\$72.50
401147	Cannula	\$14.99
401151	Chisel	\$8.10
401154	Clamp Bone Holding	\$7.00
401160	Bookwalter Blades Refurbish	\$5.00
401161	Bookwalter Horizontal Bar	\$25.00
401162	Bookwalter Ratchet	\$32.96
401163	Bookwalter Blades - Replace	\$46.80
401164	Bookwalter Post Coupeler	\$30.00
401165	Bookwalter Ring	\$20.00
401166	Bookwalter Table Post	\$25.00
401170	Clamps, Vascular/Bulldog	\$10.00
401176	Clamp Towel Clips	\$6.30
401178	Clip Applying Forceps	\$15.00
401186	Curette, Dual Head/Micro	\$25.00
401196	Dilator, Sound	\$7.00
401199	Drill Bits-Burrs	\$10.00
401210	Elevator, Periosteal/Rib/Freer/Bone	\$5.00
401212	Elevator, Nasal/Dual/Micro	\$15.00
401219	Forcep, Reinsulate/Resolder Cord	\$89.99
401221	Forcep, Debakey/Delivery	\$6.00
401223	Forcep Micro, Jeweler	\$18.22
401224	Forcep, Tissue/Adson	\$5.00
401225	Forcep New Carbide	\$15.00
401226	Forcep Bipolar	\$15.30
401227	Forcep Bipolar New Cap	\$59.40
401228	Forcep Reinsulate	\$89.99
401229	Forcep Bipolar, Re-insulate, New Cap	\$89.99
401230	Forcep New Stopper	\$30.00
401239	Gouges	\$10.00
401245	Hooks General Surgery	\$8.10
401246	Hooks Micro	\$25.00
401259	Knives, Amputation/Micro Eye/Regular	\$20.00
40144	Knife Handle	\$0.00
401275	Laryngeal Blade Refurbish	\$10.00
401276	Laryngeal Blade, Replace Lamp	\$21.60
401277	Laryngeal Blade, Replace Pin	\$20.00
401278	Laryngeal Blade, Replace Ball	\$20.00
401280	Mallet Refurbish	\$5.00
401281	Mallet, Replace Nylon Head	\$54.65
401282	Mallet, Replace Handle	\$79.39
401283	Mallet, Secure Handle	\$19.80
401288	Micro Instruments/Misc.	\$20.00
401289	Micro Manipulators	\$25.00
401291	Mirror Dental, Refurbish	\$5.40
401292	Mirror Dental-secure mirror	\$17.00
401293	Mouth Gag Refurbish	\$6.70
401294	Mouth Gag -replace silicone tube	\$14.40
401301	Mouth Gag, color coat	\$29.63
401295	Nail Clippers	\$9.00
401296	Needle Holder, Refurbish Only	\$9.36
401297	Needle Holder, New Carbide Jaws	\$18.45
401298	Needle Holder, Shape New Seat	\$22.05
401299	Needle Holder-Castro, Refurbish	\$25.00
401300	Needle Holder, Diamond Dust	\$44.10
401310	Osteotomes/Lambotte Refurbish	\$7.00
401311	Osteotomes-2 sided - Carbides	\$79.79
401324	Pin/Wire Cutter Refurbish	\$25.00
401325	Pin/Wire Cutter-new carbides	\$206.98
401342	Pin/Wire Cutter, new jaws	\$348.27
401329	Pliers	\$12.00
401330	Probes	\$6.00
40118	Punch	\$22.12
401332	Rasps Refurbish	\$7.00
401333	Rasps-replace carbides	\$49.80

BPI Medical Instrument Service

Code	Repair Description	Price
401334	Reamers, Twist/Hip(chesee grater)	\$30.00
401336	Reamers, Acetabular	\$40.00
401337	Reamers, Flex/Rigid/Tapered	\$25.00
401343	Blades, Retractor, Refurbish	\$20.00
401355	Retractor, Locking-Gelpi/Weitliner	\$10.35
401361	Retractor, Hand Held/Rake	\$5.00
401153	Ring-handled Instrument	\$7.45
401380	Rongeur, General	\$22.05
401382	Rongeur Kerrison	\$25.00
401400	Scissors General/Iris/Wire/Mayo Metz	\$4.41
401402	Scissors Delicate/Serrated	\$8.91
401404	Scissors, Supercut/Carbide	\$5.94
401416	Scissors, Micro Ear/Castro Viejo/Micro	\$17.10
401424	Snare, Ear/Nasal/Tonsil	\$17.00
401432	Speculum GYN/Eye Wire Refurbish	\$15.00
401433	Speculum replace nut	\$13.96
401434	Speculum Nasal/Eye Ratchet Refurbish	\$20.00
401436	Speculum color coat	\$80.09
401437	Speculum weighted	\$10.00
401440	Stringers Refurbish	\$5.00
401441	Stringers-new pin	\$18.00
401442	Stringers-straighten pin	\$5.00
401444	Suction, Poole/Frazier/w.Needle/Coagulation, Refurbish	\$10.00
401445	Suction secure tube	\$6.00
401447	Suction, Yankauer	\$8.00
401453	Suction Tube, Micro	\$25.00
401313	Tray	\$30.00
401469	Trocar includes Pyramidal	\$9.90
401484	Verres needle Refurbish	\$22.00
401485	Verres needle -new tube	\$94.94
401500	Finish titanium anodize	\$44.10
401501	Finish diamond dust	\$44.10
401502	Finish gold dip	\$2.88
401510	Color coat-ring handle ea	\$2.25
401513	Color coat-multi color ea.color	\$3.15
401514	Insulation	\$55.12
401523	Major Inst. Screw (rongeurs, lap instruments, large retractors, bone clamps, bone forceps, pin & bolt cutters)	\$10.49
401524	Spring	\$15.94
401525	Pin	\$15.00
401604	<i>Lap replace insulation</i>	\$31.50
401605	<i>Lap replace jaw-pin</i>	\$25.00
401606	<i>Lap solder</i>	\$15.00
401610	<i>Lap align and adjust</i>	\$10.00
401611	<i>Lap sharpen only</i>	\$15.00
401612	<i>Lap bovie adapter</i>	\$25.00
401613	<i>Lap color coat handle</i>	\$48.60
401614	<i>Lap color coat ratchet handle</i>	\$41.24
401615	<i>Lap color coat rotator</i>	\$28.80
401616	<i>Lap continuity test</i>	Quote
401617	<i>Lap replace control rod</i>	\$49.75
401618	<i>Lap replace control rod ball</i>	\$10.05
401620	<i>Lap free frozen control rod</i>	\$30.00
401622	<i>Lap I & j hook reinsulate</i>	\$34.20
401625	<i>Taping per ring</i>	\$0.51
401626	<i>Lap new hinges</i>	\$31.50
401629	<i>Lap new screw</i>	\$15.49
401630	<i>Lap new shaft</i>	\$274.98
401631	<i>Lap ratchet mech. Repair</i>	\$20.00
401632	<i>Lap machine rotator</i>	\$124.99
401633	<i>Lap stopcock replacement</i>	\$49.50
401634	<i>Lap stopcock handle</i>	\$24.95
401644	<i>Lap straighten</i>	\$10.00
401645	<i>Lap remove dents</i>	\$15.00
401646	<i>Lap new cap</i>	\$67.49
401647	<i>Lap weld</i>	\$37.50
401648	<i>Lap new rotator</i>	\$72.50
401649	<i>Lap new luerlock</i>	\$19.90
401651	<i>Lap free action lube</i>	\$15.00
401652	<i>Lap needle holders, replace carbides</i>	\$134.99

BPI Medical Electric Equipment Service

Code	Option	Price
445001	Base Complete diagnostic of motor coil current. Clean and lubricate all internal parts. Inspect unit for proper operation and adjust as required. Check RPM. Clean Contacts. Replace all bearings, O-rings and shaft seals.	
445002	PCBs & Sensors Replace hall effect sensors and PCBs.	
445003	MCM Replace motor control module.	
445004	Coil Replace motor coil.	
Bien Air, Hall Microchoice Bien Air 111.54.01, 111.55.01E, 111.74.15, Hall Microchoice 5020-021, 5020-022, 5020-023, 5020-024, 5020-025		
445005	Base	\$270.00
Concept/Linvatec 9932, 9952, 9962		
445006	Base	\$405.01
445007	PCBs & Sensors	\$90.00
Dyonics EP1, PS3500EP		
445008	Base	\$360.00
445009	PCBs & Sensors	\$90.00
Hall Dermatome 8821-01		
445011	Base	\$360.00
445012	Coil	\$225.00
445015	Calibration & Parts	\$309.65
Hall Micro E 5040-001, 5040-002, 5040-003, 5040-007, 5040-008, 5040-051, 5040-052, 5040-058		
445021	Base	\$360.00
445022	PCBs & Sensors	\$180.00
Hall Versipower 5071-001, 5071-003, 5071-004		
445031	Base	\$270.00
445032	PCBs & Sensors	\$67.50
445033	MCM	\$450.01
Linvatec C9824, C9828, C9840		
445041	Base	\$360.00
445042	PCBs & Sensors	\$90.00
Lorenz 50-4002, 50-4042		
445043	Base	\$270.00
Padgett "B" Dermatome		
445044		Quote
445015	Calibration & Parts	\$309.65
Stryker Shavers 272-704, 272-704-100, 270-601, 275-601, 275-601-500, 275-701, 275-704		
445051	Base	\$225.00
445052	PCBs & Sensors	\$45.00
445053	Coil	\$315.00
Stryker 12K Shavers 270-701-500, 272-704-500		
445061	Base	\$225.00
445062	PCBs & Sensors	\$315.00
445063	Coil	\$225.00
445064	Replace Cable	\$720.01
Stryker EHD 296-79, 296-92, 296-94, 296-96, 296-97, 296-98		
445071	Base	\$360.00
445072	PCBs & Sensors	\$180.00
445073	Coil	\$180.00
Styker Cast Cutter 810, 840, 848		
445081	Base	\$270.00
445082	Coil	\$270.00
Stryker 2100 2102, 2104, 2106, 2107,2108		
445091	Base	\$337.50
445092	MCM & Coil	\$450.01
Stryker 4100 4100, 4103, 4106, 4107, 4108, 4200, 4205, 4206, 4208		
445101	Base	\$225.00
445102	PCBs & Sensors	\$135.00
445103	MCM	\$405.01
445104	Coil	\$90.00

BPI Medical Electric Equipment Service

Code	Option	Price
Stryker command II	2296-(10, 12, 17, 18, 31, 34, 37, 210, 212, 231, 234, 237), 296-(10, 12, 31, 34, 37)	
445111 Base		\$270.00
445112 PCBs & Sensors		\$90.00
445113 Coil		\$315.00
Stryker Command II	2296 80, 2296-88, 296-80	
445115 Base		\$270.00
445116 PCBs & Sensors		\$315.00
445117 Coil		\$315.00
Stryker	2296-100 Straight Drill 100K II & 2296-300 Impaction Drill	
445121 Base		\$180.00
445122 PCBs, Sensors & Coil Assembly		\$630.01
Stryker TPS	5100-10, 5100-15, 5100-25, 5100-31, 5100-34, 5100-37	
445141 Base		\$180.00
445142 PCBs & Sensors		\$180.00
445143 Coil		\$202.50
Stryker TPS	5100-88, 5100-99	
445151 Base		\$180.00
445152 Replace Throttle PCB		\$405.01
445153 Replace Coil and Coil PCB		\$218.01
Stryker Core	5400-100,31,34,37 MD #S	
445191 Base		\$260.44
445192 Replace Throttle PCB		\$260.44
445193 Replace Coil and Coil PCB		\$282.29
Stryker Core	5400 Series 88 / 89 MD #S	
445155 Base		\$268.26
445156 Replace Throttle PCB		\$291.41
445157 Replace Coil and Coil PCB		\$306.27
Xomed	Trease/Skeeter Drill	
445161 Base		\$157.50
445162 Coil		\$216.00
445163 Cable		\$67.50
Xomed	18-97200	
445169 Base		\$360.00
445170 PCBs & Sensors		\$180.00
Xomed	18-83200, 18-96200	
445171 Base		\$180.00
445172 PCBs & Sensors		\$67.50
Stryker Simple Attachments	296-80-110, 296-80-112, 4103-(110, 135, 160), 5100-15-40, 5100-15-41, 5020-028, 5020-029	
445201 Base	Inspect, clean, lube & replace bearings where required	\$90.00
Stryker Complex Attachments	2296-80-(34, 134), 296-80-(62, 125), 4100-(34, 62, 125, 126, 235, 260, 355), 4103-(62, 125, 126, 210, 213, 235, 260, 435), 5100-10-(34, 48, 50, 52, 70, 72)	
445211 Base	Inspect, clean, lube & replace bearings where required	\$270.00
Chuck	296-80-131, 4100-(131, 132, 171, 231), 4103-(131, 133, 180, 231), 4103-82-131, 5020-(30, 31)	
445221 Base	Inspect, clean, lube & replace bearings where required	\$135.00
445222 Replace		\$135.00
3M	L 375 Battery Charger	
445231 LEVEL 1		Quote
445232 LEVEL 2		Quote
	Light Sources	
	CLV-U20/U40	
445241 Minor	Complete diagnostic using mfg specifications. Disassemble and remove foreign matter. Check all connections for tightness. Visual inspection for wear/heat damage, cold solder joints. Replace minor parts as required. Verify air pump output and seal integrity. Verify battery output, replace as required.	Quote
445242 Major	Complete diagnostic using mfg specifications. Disassemble and remove foreign matter. Check all connections for tightness. Visual inspection for wear/heat damage, cold solder joints. Replace minor parts as required. Verify air pump output and seal integrity. Verify print head operation. Verify battery output, replace as required. Replace major assemblies and parts.	\$787.50

BPI Medical Electric Equipment Service

Code	Option	Price
Sony Video Printer 5200, 5600		
445251	Minor	Complete diaganstic using mfg specifications. Disassemble and remove foreign matter. Check all connections for tightness. Visual inspection for wear/heat damage, cold solder joints. Replace minor parts as required. Verify battery output, replace as required. \$787.50
445252	Major	Complete diaganstic using mfg specifications. Disassemble and remove foreign matter. Check all connections for tightness. Visual inspection for wear/heat damage, cold solder joints. Replace minor parts as required. Verify battery output, replace as required. Replace major assemblies and parts. \$1,057.50
Olympus Processor CV100/200		
445261	Minor	Complete diaganstic using mfg specifications. Disassemble and remove foreign matter. Check all connections for tightness. Visual inspection for wear/heat damage, cold solder joints. Replace minor parts as required. Verify battery output, replace as required. Quote
445262	Major	Complete diaganstic using mfg specifications. Disassemble and remove foreign matter. Check all connections for tightness. Visual inspection for wear/heat damage, cold solder joints. Replace minor parts as required. Verify battery output, replace as required. Replace major assemblies and parts. \$1,440.00
Hall Micro E Console		
445271	Level 1	Test all functions. Minor electrical repairs . Clean all internal components. Quote
445272	Level 2	Test all functions. Major board levelectrical repairs or component replacement . Clean all internal components. Quote
Stryker 5100-8 Footswitch		
445281	Level 1	Minor electrical repair. Clean all internal components. Test all functions. \$202.50
445282	Level 2	Major electrical repair. Clean all internal components. Test all functions. Major board repair or component replacement . \$360.00
Additional Repairs		
445291	A	Corrosion \$108.00
445292	B	Extreme Corrosion \$216.00
445293	C	Dent Removal \$45.00
445294	M	Machine Shop Work \$72/hr
445295	S	Switch Repair \$202.50
Hall Burr Guard 5020-60, 5020-61, 5020-62, 5020-68		
445301		\$45.00
445311	Bovie Cords & Misc.Cables	\$27.00
445312	Stryker Cable 5100-4 Repair/Exchange	\$256.50
445313	Stryker Command II 296-4 Repair/Exchange	\$292.50
Parts and Consoles		
445950	Stryker 5100-10 Motor Coil	\$147.67
445951	Styker Motor Coils (Large)	\$157.28